

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010777/QGS3Q2

Date: 26/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0000262
Claimant Vehicle No :	SMR3784C	Insured Vehicle No :	GX2498A
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0001989

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3784C		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR2F77510
Reg. Date:	31/12/2019 (Man. Year: 2019)	Chassis No:	JTDZS3EU10J052083
Colour:	Brown	Odometer:	38249 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,756.12	3,691.50	4,064.62	52.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,580.00	1,490.00	48.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,826.12	5,271.50	5,554.62	51.31
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	10,826.12	4,200.00	6,626.12	61.20
+ GST 7.00/7.00% (S\$)	757.83	294.00	463.83	61.21
Nett Amount (S\$)	11,583.95	4,494.00	7,089.95	61.20
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,821.45		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020 Inspected At:

My Car Consultant Pte Ltd - Ubi (HQ)
53 Ubi Ave 1, #01-33 Paya Ubi

Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2020)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3784C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	698.00 FL	*698.00 FL
2	1		*REAR BUMPER LOWER	Scratched	412.00 FL	*412.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Serviceable	224.00 FL	*- FL
4	1		*TAILAMP LH	Serviceable	489.00 FL	*- FL
5	1		*REAR FENDER LH	Dented	798.00 FL	*798.00 FL
6	1		*REAR FENDER COWLING LH	Serviceable	159.00 FL	*- FL
7	1		*REAR FENDER QUARTER GLASS MLDG LH	Necessary	189.00 FL	*189.00 FL
8	1		*ROCKER PANEL GARNISH LH	Deformed	798.00 FL	*722.00 FL
9	1		*REAR DOOR LH	Dented	1,214.00 FL	*1,115.00 FL
10	1		*REAR OUTER MOULDING LH	Serviceable	124.00 FL	*- FL
11	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	198.00 FL	*- FL
12	1		*REAR KNUCKLE ARM LH	Serviceable	487.00 FL	*- FL
13	1		*REAR KNUCKLE ARM BEARING LH	Jammed	148.00 FL	*148.00 FL
14	1		*REAR AXLE	Serviceable	1,985.00 FL	*- FL
15	1		*REAR SHOCK ABSORBER LH	Serviceable	418.50 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*SET REAR FENDER COWLING CLIPS	Serviceable	50.00 FS	*- FS
18	1		*REAR SPORTS RIM RH	Scratched	800.00 FS	*600.00 FS
19	1		*REAR TYRE RH	Serviceable	250.00 FS	*- FS
20	1		*SET REAR STICKER	Serviceable	300.00 FS	*- FS
21	1		*BRAKE FLUID	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,841.50	4,712.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,085.38	1,020.50
Total Parts (\$\$)	7,756.12	3,691.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	REMOVE AND TRANSFER REVERSE SENSOR	New	120.00	30.00
3	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
4	REMOVE AND REFIT REAR UNDERCARRIAGE	New	400.00	0.00
5	TO RESPRAY UNDERCOATING	New	150.00	30.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	30.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	800.00
Gross Labour Cost (S\$)			3,070.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >