

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010783/QGS3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHC4130X	Insured Vehicle No :	SHC8905B
Date of Loss: 05/10/2020	Nature of Claim: TP	Claim No: MCT20100079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4130X		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZRS098559
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU903573010
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,869.68	600.24	19,269.44	96.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,535.00	1,730.00	2,805.00	61.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	24,404.68	2,330.24	22,074.44	90.45
+ Car Rental (7.3 x S\$112.35/day) (\$\$)		814.54		
	Nett Liability (\$\$)	3,144.78		

INSPECTION

Date of Assignment:	07/10/2020	
Date Inspected:	07/10/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2020)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4130X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
2	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
3	1		*SUPPORT ,FR BUMPER RH (DISC 25%)	Broken	76.90 F	*57.68 F
4	1		*COVER ,FR BUMPER (DISC 25%)	Crumpled	495.50 F	*371.63 F
5	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
6	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
7	1		*WHEEL ,DISC FRONT	Repair	1,555.10 F	*- F
8	1		*FENDER SUB-ASSY ,FR RH	Repair	933.10 F	*- F
9	1		*PANEL SUB-ASSY ,FENDER REAR RH	Repair	824.80 F	*- F
10	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Repair	1,243.90 F	*- F
11	1		*PANEL SUB-ASSY ,FRONT DOOR RH	Repair	1,249.60 F	*- F
12	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Repair	576.00 F	*- F
13	1		*PILLAR ,FRONT BORY ,RH	Serviceable	339.40 F	*- F
14	1		*PROTECTOR ,FR FENDER RH	Serviceable	90.40 F	*- F
15	1		*PAD ,FR WHEEL RH	Serviceable	57.70 F	*- F
16	1		*LINER ,FR FENDER RH	Serviceable	198.40 F	*- F
17	1		*UNIT ,HEADLAMP RH	Serviceable	2,558.90 F	*- F
18	1		*LAMP ASSY ,FOG ,RH	Serviceable	910.20 F	*- F
19	1		*COVER ,ENGINE UNDER CENTER	Serviceable	94.50 F	*- F
20	1		*SET COVER ASSY ,ENGINE UNDER CENTER	Serviceable	452.80 F	*- F
21	1		*COVER ASSY ,ENGINE	Serviceable	180.10 F	*- F
22	1		*SPOILER SUB-ASSY ,REAR	Serviceable	1,322.10 F	*- F
23	2		*HUB & BEARING ASSY, RH & LH	Serviceable	554.20 F	*- F
24	1		*TYRE	Serviceable	126.74 F	*- F
25	1		*WHEEL ,DISC	Serviceable	1,555.10 F	*- F
26	1		*LINER ,REAR FENDER RH	Serviceable	135.80 F	*- F
27	2		*PATCH ,SIDE PANEL REAR END ,RH & LH	Serviceable	33.70 F	*- F
28	1		*WIRE REAR DOOR RH	Serviceable	206.70 F	*- F
29	1		*CHECK ASSY ,REAR DOOR	Serviceable	153.50 F	*- F
30	1		*HINGE ASSY ,REAR DOOR LOWER RH	Serviceable	73.30 F	*- F
31	1		*HINGE ASSY ,REAR DOOR UPPER RH	Serviceable	83.30 F	*- F
32	1		*WIRE FRONT DOOR ,LH	Serviceable	445.70 F	*- F
33	1		*HINGE ASSY ,FRONT DOOR LOWER RH	Serviceable	92.10 F	*- F
34	1		*HINGE ASSY ,FRONT DOOR UPPER RH	Serviceable	82.10 F	*- F
35	1		*CHECK ASSY ,FRONT DOOR	Serviceable	153.50 F	*- F
36	1		*COVER ,OUTER MIRROR ,RH	Serviceable	89.50 F	*- F
37	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Serviceable	1,373.50 F	*- F
38	1		*TYRE	Serviceable	126.74 F	*- F
39	1		*HUB & BEARING ASSY ,RH & LH	Serviceable	554.20 F	*- F
40	1		*GRILLE SUB-ASSY	Serviceable	335.60 F	*- F
41	1		*GRILLE RADIATOR	Serviceable	165.00 F	*- F
42	1		*BRACKET ,FR BUMPER	Serviceable	99.80 F	*- F
43	1		*SUPPORT FR BUMPER LH	Serviceable	82.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Total Parts (S\$)					19,869.68	600.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	500.00
2	SPRAY PAINT	New	2,970.00	1,150.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
4	TO TRANSFER DOOR MECHANISM	New	240.00	0.00
5	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			4,535.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >