

VEHICLE NO : SGD 1208 H

MODEL : MIT ECLIPSE CROSS 1.5

WIP : 58151

Material	:	\$	<u>3,531.22</u>
Labour	:	\$	<u>2,760.00</u>
Sub-Total	:	\$	<u>6,291.22</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>400.00</u>
Total	:	\$	<u>5,891.22</u>
GST 7%	:	\$	<u>412.39</u>
Grand Total	:	\$	<u>6,303.61</u>
Finalise By/Date : <u>LOI 30/10/2020</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK _____ WORKING DAYS + _____ Days (_____ Weekends)
+ _____ Days (Public holiday)
= _____ Days

☐ TP claim _____

☐ Claim GIA / LTA fee \$ _____

☐ Claim Loss of Use / Loss of Rental

☐ Claim Medical Fee / Others = \$ _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/10/2020	Cust No/Name	/TANG POH CHEE
	Reg No/Reg Date	SGD1208H / 11/02/2019
	Date In/Mileage	08/10/2020/ 40845
	Chassis/Package	JMAXTGK1WKZ00012C /CS3P
	Engine No	4B40GD5353
	Make/Model	MIT/ECLIPSE CROSS 1.5 STYLE SR (T23)
	Colour/Trim	W13 SILKY WHITE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	30/10/2020/ 13:27	BLK	260 / AiTing	58151			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 900.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR								✓ 100.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
X EXC INSURANCE EXCESS								-400.00
M SUNDRY SUPPLY LH FRONT SPORTS RIM → Supp								730.00
X	HEADLAMP ASSY,LH	1.00	?	1976.00	23.00		1521.52	
X	LAMP A,T/SIG & FOG,FR LH	1.00	?	506.00	23.00		389.62	
X	FACE,FR BUMPER	1.00	✓	714.00	23.00		549.78	
X	BRACKET,FR BUMPER SIDE,LH	1.00	✓	18.00	23.00		13.86	
X	FENDER,FR LH	1.00	✓	599.00	23.00		461.23	
X	MOULDING,FR WHEEL ARCH,LH	1.00	✓	151.00	23.00		116.27	
X	FRONT CORNER EXTENSION	1.00	✓	238.00	23.00		183.26	
X	FRONT BUMPER GARNISH → Supp	1.00		384.00	23.00		295.68	
Z TEXT AIG OD CLAIM, UIL CLAIM SLM1779U								

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/10/2020	Cust No/Name	/TANG POH CHEE
	Reg No/Reg Date	SGD1208H / 11/02/2019
	Date In/Mileage	08/10/2020/ 40845
	Chassis/Package	JMAXTGK1WKZ00012C /CS3P
	Engine No	4B40GD5353
	Make/Model	MIT/ECLIPSE CROSS 1.5 STYLE SR (T23)
	Colour/Trim	W13 SILKY WHITE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	30/10/2020/ 13:27	BLK	260 / AiTing	58151

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
DOA : 05.10.20 SURVEYOR TAUFIKH LKK 08.10.20 POLICY NO : 1900012595				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,531.22	Nett	5,891.22
Labour	1,970.00	7% GST on	412.39
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,303.61
Sundry/Others	390.00		
Total(w/o GST)	5,891.22		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SGD 1208 H**

Materials

Cost (\$)

1	Front bumper garnish	384.00
Total		384.00
Less 23%		88.32
Total Materials		295.68

Labour

Cost (\$)

1	Supply LH front soprts rim	730.00
Total Labour		730.00
Taxable Amount		1,025.68
7% GST		71.80
Grand total		<u>1,097.48</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501

22

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	HEADLAMP ASSY. LH	☒ / SUPP	cm		
2	LAMP H.I / SIG FOOT, FR LH	☒ / SUPP	cm		
3	FRONT BUMPER GARNISH	☒ / SUPP	de		MZ 576673EX
4		☒ / SUPP			
5		☒ / SUPP			
6		☒ / SUPP			
7		☒ / SUPP			
8	Supply v/f sports rim	☒ / SUPP		Agreed by Taufiqh.	
9		☒ / SUPP			
10		☒ / SUPP			
11		☒ / SUPP			
12		☒ / SUPP			
13		☒ / SUPP			
14		☒ / SUPP			
15		☒ / SUPP			
16		☒ / SUPP			
17		☒ / SUPP			
18		☒ / SUPP			
19		☒ / SUPP			
20		☒ / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	9/10	Tracy
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Eclipse Cross

SURVEYOR: Luk - Tausch

R001205
SGD1208H
ALVIN (108)
40845
13.10.20 16:13

MITSUBISHI ECLIPSE CROSS 16" & 18" 2018-

Front : Left

Actual	Before	Specified Range
0°04'	0°03'	0°00' 0°30'
2°05'	2°03'	2°00' 3°00'
0°03'	0°08**	0°00' 0°06'
11°57'	11°56'	11°30' 14°30'
12°01'	11°59'	11°30' 15°00'

**Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.**

Front : Right

Actual	Before	Specified Range
0°06'	0°07'	0°00' 0°30'
2°58'	3°00'	2°00' 3°00'
0°04'	-0°01**	0°00' 0°06'
12°02'	12°03'	11°30' 14°30'
12°08'	12°10'	11°30' 15°00'

Front

**Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.**

Actual	Before	Specified Range
-0°02'	-0°04'	-0°45' 0°45'
-0°53**	-0°57**	-0°45' 0°45'
-0°05'	-0°07'	-0°45' 0°45'
0°07'	0°07'	0°01' 0°11'

Rear : Left

Actual	Before	Specified Range
-0°43'	-0°44'	-0°55' -0°25'
0°08'	0°08'	0°06' 0°11'

**Camber
Toe**

Rear : Right

Actual	Before	Specified Range
-0°54'	-0°54'	-0°55' -0°25'
0°07'	0°07'	0°06' 0°11'

Rear

**Cross Camber
Total Toe
Thrust Angle**

Actual	Before	Specified Range
0°11'	0°10'	-0°45' 0°45'
0°16'	0°16'	0°11' 0°21'
0°00'	0°00'	

Don't know
 what
 M.U.T-3
 is
 to
 Base
 all
 30
 level

All DTCs

Setting	
Item	Information
M.U.T-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	GK1W 2019MY

Done
 N/A
 A/C

All DTCs

2020.10.13

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition				
	MPI/GDI/DIESEL	GAS_OC640000		No DTCs					
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs					
	4WS/Electric Power Steering	EPS_45840000		No DTCs					
	ABS/ASC/ASTC/WSS	ASC_42080014		No DTCs					
	SRS-AIR BAG	SRS_81047305		No DTCs					
	Air Conditioner	AC_80080017		No DTCs					
	ETACS	ETACS_83040800		No DTCs					
	TPMS (with KOS)	ETACS_83040800		No DTCs					
	Meter	METER_84088001		No DTCs					
	Steering Angle Sensor	GS_SAS_47000100_ForumMUT3		No DTCs					
	AND	AND_8C080002		Non-target System					
	AUDIO (IntelligentDisplay)	AUDIO_8D080002		No DTCs					
	LIN	ETACS_83040800		Non-target System					
	KOS/OSS/IMMO/Keyless (with KOS)	ETACS_83040800		No DTCs					

All DTCs

2020.10.13

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
CORNER SENSOR/SONAR	SONAR_9D080000		No DTCs	
ACC/FCM	ACCSFCM_4B080004		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		No DTCs	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		No DTCs	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	
HUD	HUD_9E080000		No DTCs	