

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20010788/UES3Q2

**Date:** 10/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070074734

**Claimant**  
**Vehicle No :** FJ300K **Insured Vehicle No :** SLP1039G

Date of Loss: 03/10/2020 Nature of Claim: TP Claim No: 9586861129SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FJ300K</b>	Engine No:	H336E0060773
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Chassis No:	MH3SH0844KK008118
Reg. Date:	30/08/2019 (Man. Year: 2019)	Odometer:	29949 km
Colour:	Black		
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120-70 R15	Rear Tyre Size:	140-70-14
Front Left Side:	MITAS 7 mm	Rear Left Side:	MITAS 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,281.60	1,154.70	126.90	9.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	300.00	400.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,981.60</b>	<b>1,454.70</b>	<b>526.90</b>	<b>26.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	1,981.60	1,150.00	831.60	41.97
<b>+ GST 7.00/7.00% (S\$)</b>	138.71	80.50	58.21	41.97
<b>Nett Amount (S\$)</b>	<b>2,120.31</b>	<b>1,230.50</b>	<b>889.81</b>	<b>41.97</b>
<b>+ Car Rental (S\$)</b>		100.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,332.50</b>		

### INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HANDLE BAR	Serviceable	48.00 FL	*- FL
2	1		*O/S HANDLE BAR BALANCER	Scratched	20.00 FL	*20.00 FL
3	1		*O/S HANDLE BAR GRIP	Not Necessary	25.00 FL	*- FL
4	1		*O/S SIDE MIRROR	Cut	60.00 FL	*60.00 FL
5	1		*O/S FRONT ABSORBER COVER	Not fitted	38.00 FL	*- FL
6	1		*O/S FRONT ABSORBER COVER ABS STICKER	Not Necessary	30.00 FL	*- FL
7	1		*O/S SIDE FAIRING	Cut	60.00 FL	*60.00 FL
8	1		*O/S REAR SIDE FAIRING	Cut	78.00 FL	*78.00 FL
9	1		*O/S REAR SIDE FAIRING XMAX EMBLEM	Necessary	60.00 FL	*60.00 FL
10	1		*EXHAUST PIPE ASSY	Dented	687.00 FL	*687.00 FL
11	1		*EXHAUST PIPE HEAT SHIELD	Grazed	85.00 FL	*85.00 FL
12	1		*O/S STEP GARNISH COVER	Cut	68.00 FL	*68.00 FL
13	1		*O/S REAR SIDE FAIRING LOWER	Cut	30.00 FL	*30.00 FL
14	1		*O/S FRONT YAMAHA EMBLEM	Necessary	25.00 FL	*25.00 FL
15	1		*O/S SIDE FAIRING LOWER	Grazed	60.00 FL	*60.00 FL
16	1		*O/S FRONT SIGNAL LAMP	Scratched	50.00 FL	*50.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,424.00</b>	<b>1,283.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	142.40	128.30
<b>Total Parts (\$\$)</b>	<b>1,281.60</b>	<b>1,154.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	0.00
2	TO REPAIR AND REALIGN REAR EXHAUST BOX	New	50.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	350.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	250.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>700.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >