

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FJ300k

at Workshop m/s

Tandem

of

Insured:

SLP 10396

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

B12k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

446J

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: FJ300k

Yr Regn: 8 / 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha C2D300A c.c 292

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 29949

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH35H0844kk 008/18

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

120-70-R15

R:

140-70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Mitas.

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/10/20

D.O.I.

7/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

BI involved 27A83828
have video at folder

mirror 105 lower belly 245

23/10/20 2/5 @ 1150 conf. with MR Tan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) S + RS, SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLP1039G
Date of Accident : 03 October 2020

Mr Mohammad Fariz Bin Mohammad

Date : 21 October 2020

Estimate To Repair FJ300K - Yamaha CZD300A / XMAX300
Chassis No : MH3SH0844KK008118

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s handle bar <i>SVC</i>	\$ 48.00
02	1 pc	o/s handle bar balancer <i>SVC</i>	\$ 20.00
03	1 pc	o/s handle bar grip <i>nn</i>	\$ 25.00
04	1 pc	o/s side mirror <i>CUT</i>	\$ 60.00
05	1 pc	o/s front absorber cover <i>nn</i>	\$ 38.00
06	1 pc	o/s front absorber cover ABS sticker <i>nn</i>	\$ 30.00
07	1 pc	o/s side fairing <i>CUT</i>	\$ 60.00
08	1 pc	o/s rear side fairing <i>CUT</i>	\$ 78.00
09	1 pc	o/s rear side fairing xmax emblem <i>nn</i>	\$ 60.00
10	1 pc	exhaust pipe assy <i>DD</i>	\$ 687.00
11	1 pc	exhaust pipe heat shield <i>grand</i>	\$ 85.00
			\$ 1,191.00
		Less 10 %	\$ 119.10
			\$ 1,071.90
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned. <i>nn</i>	\$ 50.00
02		To repair and realign rear exhaust box. <i>nn</i>	\$ 50.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 350.00
04		Putty and spray painting of the affected portion.	\$ 250.00
			\$ 700.00
		Total	\$ 1,771.90

not Authorised
Dear
7/10/20
3 days.
L/S 11/50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SLP1039G
Date of Accident : 03 October 2020

Mr Mohammad Fariz Bin Mohammad

Date : 22 October 2020

Supplementary To Repair FJ300K - Yamaha CZD300A / XMAX300
Chassis No : MH3SH0844KK008118

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s step garnish cover C47	\$ 68.00
02	1 pc	o/s rear side fairing lower C47	\$ 30.00
03	1 pc	o/s front yamaha emblem M	\$ 25.00
04	1 pc	o/s side fairing lower 91226	\$ 60.00
05	1 pc	o/s front signal lamp SCR	\$ 50.00
			\$ 233.00
		Less 10 %	\$ 23.30
			\$ 209.70
		Total	\$ 209.70

P-1283
10%
154.7
14547
203
1163