

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010793/T1YF3E2

Date: 23/11/2020

REFERENCE

Insured/Claimant:	LOH AI LIN	Policy No:	
Date of Loss:	06/10/2020	Nature of Claim:	OD Claim No: 4331840136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ2534G		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGJH719801
Reg. Date:	27/02/2019 (Man. Year: 2018)	Chassis No:	KNAF3416MK5030251
Colour:	Dark Blue	Odometer:	14576 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,632.82	2,383.60	2,249.22	48.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,000.00	2,080.00	50.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,712.82	4,383.60	4,329.22	49.69
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	8,412.82	4,083.60	4,329.22	51.46
+ GST 7.00/7.00% (\$\$)	588.90	285.85	303.05	51.46
Nett Amount (\$\$)	9,001.72	4,369.45	4,632.27	51.46

INSPECTION

Date of Assignment: 07/10/2020
Date Inspected: 07/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
3	1		*PANEL ASSY-HOOD	Bent	1,502.00 FL	*1,502.00 FL
4	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
5	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
6	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
7	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
8	1		*GRILLE-FRONT BUMPER	Deformed	262.00 FL	*262.00 FL
9	1		*COVER-FR BUMPER	Deformed	633.00 FL	*633.00 FL
10	1		*GRILLE ASSY-RADIATOR	Cracked	328.00 FL	*328.00 FL
11	1		*ABSORBER-FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
15	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
16	1		*MOULDING-FRONT BUMPER, LH	Not Necessary	36.00 FL	*- FL
17	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,219.00 FL	*- FL
18	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
19	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
20	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- F
21	1		*GARNISH-RADIATOR GRILLE	Deformed	38.00 FL	*38.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	5,772.00	2,962.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,133.20	578.40
- Nett Item Discount on N Items 23.00/0.00% (\$\$)	5.98	0.00
Total Parts (\$\$)	4,632.82	2,383.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER, BONNET & FRT SUPPORT REPAIR LHF FENDER & RHF FENDER	New	2,000.00	800.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER & RHF FENDER	New	1,400.00	700.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SPRAY PAINT RH FRONT FENDER	New	350.00	350.00
Gross Labour Cost (S\$)			4,080.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >