

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010797/BES3Q2
Date: 16/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070052253
Claimant Vehicle No :	SMC4484R	Insured Vehicle No :	GBF8362Y
Date of Loss:	06/10/2020	Nature of Claim:	TP
		Claim No:	3586081437SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC4484R	Engine No:	G4LCJU993182
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTKU431424
Reg. Date:	30/06/2018 (Man. Year: 2018)	Odometer:	13249 km
Colour:	Silver		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,423.65	3,421.40	3,002.25	46.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,880.00	1,720.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,023.65	5,301.40	4,722.25	47.11
Approved Total (Overridden) (S\$)		4,200.00		

(S\$)	10,023.65	4,200.00	5,823.65	58.10
+ GST 7.00/7.00% (S\$)	701.66	294.00	407.66	58.10
Nett Amount (S\$)	10,725.31	4,494.00	6,231.31	58.10
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,921.45		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	958.00 FL	*789.89 FL
2	2		*REAR BUMPER RETAINER	Necessary	211.20 FL	*211.20 FL
3	1		*REAR FENDER LH	Dented	1,254.00 FL	*1,254.00 FL
4	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	254.00 FL	*- FL
5	1		*REAR FENDER INNER COWLING LH	Not Damaged	103.20 FL	*- FL
6	1		*REAR AIR VENTS LH	Not Damaged	66.20 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	182.36 FL	*182.36 FL
8	1		*TAILLAMP LH	Broken	786.30 FL	*697.80 FL
9	1		*TAILLAMP LOWER BRACKET LH	No such part	87.60 FL	*- FL
10	1		*REAR SHOCK ABSORBER LH	Not Damaged	653.20 FL	*- FL
11	1		*REAR AXLE	Not Damaged	890.00 FL	*- FL
12	1		*REAR WHEEL HUB WITH BEARING LH	Jammed	483.50 FL	*454.00 FL
13	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
14	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*REAR FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
16	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
17	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
19	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
20	1		*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
21	1		*TAILLAMP SEAL	Necessary	60.00 FS	*30.00 FS
22	1		*TAILLAMP CLIPS	No such part	50.00 FS	*- FS
23	1		*REAR RIM LH	Cut	650.00 FS	*400.00 FS
24	1		*REAR TYRE LH	Not Damaged	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,609.56	4,139.25
- List Item Discount on L Items 20.00/20.00% (\$)	1,185.91	717.85
Total Parts (\$)	6,423.65	3,421.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REVERSE SENSOR	New	150.00	60.00
2	R&R REAR WINDSCREEN	New	250.00	120.00
3	R&R FUEL TANK PIPE	New	150.00	70.00
4	R&R REAR UNDERCARRIAGE PARTS	New	250.00	150.00
5	R&R REAR TYRE AND BALANCING	New	80.00	30.00
6	WHEEL ALIGNMENT	New	120.00	60.00
7	CHECK WIRING	New	100.00	30.00
8	UPHOLSTERY	New	300.00	100.00
9	PANEL BEAT	New	1,000.00	600.00
10	RUST PROOFING	New	200.00	60.00
11	SPRAY PAINT	New	1,000.00	600.00
Gross Labour Cost (S\$)			3,600.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >