

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2059H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	1,106.00	1,106.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET - LH	BROKEN	35.60	35.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER REINFORCEMENT BRACKET LH	NOT NECESSARY	80.30	-
1	REAR BUMPER UNDERCOVER	NOT NECESSARY	228.00	-
1	REAR BUMPER REFLECTOR - LH	CUT	32.00	32.00
	LESS 20% DISCOUNT		-386.46	-239.12
			1,545.84	956.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	50.00	50.00
1	REAR LEFT FENDER ADVERTISEMENT STICKER (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			335.70	200.00
<u>LABOUR</u>				
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		100.00	30.00
			700.00	540.00
GRAND TOTAL			2,581.54	1,696.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,350.00

Report Ref No. NS/INC20010812/Evd3e2


CHEN TSUE YEE

Automotive Assessor


K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.