

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010816/T1VD3E2

Date: 20/10/2020

REFERENCE

Insured/Claimant:	TAN HUI LEE	Policy No:	1800063172
Date of Loss:	05/10/2020	Nature of Claim:	OD
		Claim No:	0769001798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3429T		
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Engine No:	G4FGJH695449
Reg. Date:	04/06/2018 (Man. Year: 2017)	Chassis No:	KNAFJ411MJ5764930
Colour:	Grey	Odometer:	36963 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,592.00	1,500.80	91.20	5.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,650.00	800.00	32.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,042.00	3,150.80	891.20	22.05
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,742.00	2,850.80	891.20	23.82
+ GST 7.00/7.00% (S\$)	261.94	199.56	62.38	23.81
Nett Amount (S\$)	4,003.94	3,050.36	953.58	23.82

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Cut	810.00 FL	*810.00 FL
3	1		*PANEL-FENDER, LH	Bent	376.00 FL	*376.00 FL
4	1		*GUARD ASSY-FRONT WHEEL, LH	Not Necessary	95.00 FL	*- FL
5	1		*COVER-FR BUMPER	Deformed	633.00 FL	*633.00 FL
6	1		*BRACKET-FR BUMPER SIDE MTG, LH	Not Necessary	13.00 FL	*- FL
7	1		*DUCT ASSY-AIR CURTAIN, LH	Not Necessary	6.00 FL	*- FL
8	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,985.00	1,871.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	393.00	370.20
Total Parts (\$\$)	1,592.00	1,500.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER & LHF FENDER	New	1,600.00	800.00
2	RESPRAY FRT BUMPER & LHF FENDER	New	700.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			Gross Labour Cost (\$\$)	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >