

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010820/KTF3Q2

Date: 20/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29138106AL2

Claimant
Vehicle No : SMR2770Z

Insured Vehicle No : SLU3553Z

Date of Loss: 06/10/2020

Nature of Claim: TP

Claim No: 629511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR2770Z**

Make & Model: MERCEDES-BENZ GLE400, 3.0 4MATIC (R20 LED SR) (A)

Engine No: 27682130961594

Reg. Date: 27/12/2019 (Man. Year: 2018)

Chassis No: WDC2923562A137450

Colour: Dark Blue

Odometer: 5788 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/50R20

Rear Tyre Size: 275/50R20

Front Left Side: Pirelli 9 mm

Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm

Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,540.00	3,799.94	17,740.06	82.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	680.00	2,850.00	80.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,070.00	4,479.94	20,590.06	82.13
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	25,070.00	3,500.00	21,570.00	86.04
+ GST 7.00/7.00% (S\$)	1,754.90	245.00	1,509.90	86.04
Nett Amount (S\$)	26,824.90	3,745.00	23,079.90	86.04

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 20/10/2020 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2020)
Parts:	192	MERCEDES-BENZ GLE400 3.0 4MATIC (R20 LED SR) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR2770Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	7,000.00 F	*- FL
2	1		*TAILGATE WEATHERSTRIP	Serviceable	500.00 F	*- FL
3	1		*TAILGATE MERCEDES LOGO	Serviceable	150.00 F	*- FL
4	1		*TAILGATE EMBLEM GLE 400	Serviceable	120.00 F	*- FL
5	1		*TAILGATE EMBLEM 4 MATIC	Not Necessary	120.00 F	*- FL
6	1		*TAILGATE LAMP LH	Serviceable	700.00 F	*- FL
7	1		*TAILGATE LAMP RH	Serviceable	700.00 F	*- FL
8	1		*TAILLAMP LH	Serviceable	900.00 F	*- FL
9	1		*TAILLAMP RH	Serviceable	900.00 F	*- FL
10	1		*REAR BUMPER	Dented/Cut	2,500.00 F	*1,615.45 FL
11	1		*REAR BUMPER SPONGE	Serviceable	250.00 F	*- FL
12	1		*REAR BUMPER RETAINER LH	Serviceable	95.00 F	*- FL
13	1		*REAR BUMPER RETAINER RH	Serviceable	95.00 F	*- FL
14	1		*REAR BUMPER TOWING COVER	Missing	200.00 F	*56.00 FL
15	1		*REAR BUMPER LOWER COVER TRIM	Cracked	800.00 F	*743.32 FL
16	1		*REAR BUMPER DIFFUSER CHROME	Dented	800.00 F	*788.50 FL
17	1		*REAR BUMPER REFLECTOR LH	Serviceable	50.00 F	*- FL
18	1		*REAR BUMPER REFLECTOR RH	Serviceable	50.00 F	*- FL
19	4		*REAR BUMPER SENSOR	Serviceable	800.00 F	*- FL
20	10		*REAR BUMPER CLIP	Necessary	80.00 F	*80.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Repair	1,800.00 F	*- FL
22	1		*END PANEL	Repair	2,000.00 F	*- FL
23	1		*REAR NUMBER PLATE & HOLDER	Bent	80.00 FS	*45.00 FS
24	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS
25	1		*CERAMIC COATING	Necessary	800.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,540.00	4,128.27
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	328.33
Total Parts (\$\$)	21,540.00	3,799.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,600.00	300.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	200.00	20.00
3	TO REMOVE & REFIT ALL SENSOR	New	250.00	60.00
4	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	200.00	0.00
5	TO APPLY ANTI RUST COATING	New	80.00	0.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	300.00
Gross Labour Cost (\$\$)			3,530.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >