

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010822/USD3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN31189619033

Claimant Vehicle No : SLU2185J **Insured Vehicle No :** SLJ2576Y

Date of Loss: 06/10/2020 Nature of Claim: TP Claim No: SNM20D203733/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU2185J**
 Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR0A31736
 Reg. Date: 27/11/2017 (Man. Year: 2017) Chassis No: JTDGG20W90J008280
 Colour: Grey Odometer: 180452 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,159.96	3,686.57	4,473.39	54.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,000.00	1,760.00	46.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,919.96	5,686.57	6,233.39	52.29
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	11,919.96	4,500.00	7,419.96	62.25

INSPECTION

Date of Assignment: 14/10/2020
 Date Inspected: 08/10/2020 Inspected At: Joo Lee Motor Workshop (HQ)
 No 1 Kaki Bukit Ave 6, #02-29
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU2185J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	165.58 FL	*165.58 FL
2	1		*REAR TAILGATE	Badly Dented	1,566.25 FL	*1,566.25 FL
3	1		*REAR TAILGATE OUTER CHROME MOULDING	Not Necessary	383.80 FL	*- FL
4	2		*REAR TAILGATE DAMPERS	Not Necessary	423.00 FL	*- FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	485.50 FL	*- FL
6	2		*REAR TAILGATE LAMPS	Not Necessary	665.80 FL	*- FL
7	1		*REAR TAILGATE LOCK	Dented/Shorted	350.96 FL	*350.96 FL
8	1		*REAR TAILGATE LOGO	Necessary	68.50 FL	*68.50 FL
9	1		*REAR TAILGATE RUBBER	Twisted/Necessary	370.50 FL	*370.50 FL
10	1		*REAR TAILGATE ELEGANCE EMBLEM	Necessary	85.00 FL	*85.00 FL
11	1		*REAR TAILGATE VALVE MATIC EMBLEM	Necessary	72.00 FL	*72.00 FL
12	2		*REAR TAILLAMPS	Not Necessary	971.00 FL	*- FL
13	2		*REAR TAILLAMP PANELS	Not Necessary	1,188.00 FL	*- FL
14	1		*REAR END PANEL	Dented/Bent	596.50 FL	*596.50 FL
15	1		*REAR END PANEL INNER GARNISH	Twisted	253.20 FL	*253.20 FL
16	1		*REAR SMART KEYLESS SENSOR	Cracked	189.50 FL	*189.50 FL
17	1		*REAR BUMPER	Dented/Deformed	991.76 FL	*625.10 FL
18	2		*REAR BUMPER BRACKETS	Not Necessary	177.00 FL	*- FL
19	1		*REAR BUMPER REFLECTORS	N/s Cracked	173.90 FL	*68.50 FL
20	1		*REAR BUMPER SIDE RETAINERS	N/s Bent	128.86 FL	*50.50 FL
21	1		*REAR FLOOR BOARD	Not Necessary	280.00 FL	*- FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
24	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*250.00 FS
25	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,556.61	4,802.09
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,396.65	1,115.52
Total Parts (\$\$)	8,159.96	3,686.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	150.00	60.00
7	PANEL BEATING	New	1,500.00	700.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	900.00
Gross Labour Cost (\$\$)			3,760.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >