

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20010823/GSD3E2  
**Date:** 14/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800063172  
**Claimant Vehicle No** : FBQ7585U **Insured Vehicle No :** SMA3429T  
Date of Loss: 05/10/2020 Nature of Claim: TP Claim No: 0769001798SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ7585U**  
Make & Model: YAMAHA TMAX530, 530cc (DX) Engine No: J415E007545  
Reg. Date: 16/05/2017 (Man. Year: 2017) Chassis No: JYASJ145000003836  
Colour: Black Odometer: 3509 km  
Engine Capacity: 530 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R15 Rear Tyre Size: 160/60 R15  
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 07/10/2020  
Date Inspected: 09/10/2020 Inspected At: Mcs Auto (HQ)  
1100 Serangoon Rd  
Singapore 328195  
Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
2	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
3	1		*CLUTCH LEVER	Cut	0.00 F	*- F
4	1		*SIDE FAIRING	Cut	0.00 F	*- F
5	1		*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
6	1		*FAIRING SHIELD	Cut	0.00 F	*- F
7	1		*REAR FAIRING	Cut	0.00 F	*- F
8	1		*FAIRING LOWER	Cut	0.00 F	*- F
9	1		*STEP BOARD	Cut	0.00 F	*- F
10	1		*SIDE STAND	Cut	0.00 F	*- F
11	1		*MAIN STAND	Cut	0.00 F	*- F
12	1		*EXHAUST MUFFLER ASSY	Cracked	0.00 F	*- F
13	1		*EMBLEM	Necessary	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00</b>
						<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >