

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20010824/ASD3E2

**Date:** 21/12/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN16374719033
<b>Claimant Vehicle No :</b>	SLT3493T	<b>Insured Vehicle No :</b>	SLD1866Z
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203722/C02/TKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3493T	Engine No:	CAK007354
Make & Model:	AUDI S4, 3.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZ8K6AA083255
Reg. Date:	07/01/2010 (Man. Year: 2009)	Odometer:	157143 km
Colour:	Pink		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,134.00	4,112.70	8,021.30	66.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	1,870.00	4,180.00	69.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,184.00</b>	<b>5,982.70</b>	<b>12,201.30</b>	<b>67.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,184.00</b>	<b>4,700.00</b>	<b>13,484.00</b>	<b>74.15</b>

### INSPECTION

Date of Assignment:	07/10/2020		
Date Inspected:	08/10/2020	Inspected At:	8 Kaki Bukit Avenue 4 Premier #01-49
Estimated Period of Repair:	5.0 days		Repairer : 1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2020)
<b>Parts:</b>	143	AUDI S4 3.0 TFSI QU S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT3493T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR LH	Dented	2,920.30 FL	*2,111.00 FL
2	1		*DOOR HANDLE LH	Repair	500.30 FL	*- FL
3	1		*DOOR HANDLE SENSOR LH	Not Necessary	330.75 FL	*- FL
4	1		*DOOR ROCKER PANEL PROTECTOR LH	Cut	810.32 FS	*480.00 FS
5	1		*DOOR POWER WINDOW LH	Not Necessary	666.70 FL	*- FL
6	1		*REAR FENDER LH	Repair	1,332.00 FL	*- FL
7	1		*REAR FENDER INNER SHIELD LH	Not Necessary	398.40 FL	*- FL
8	1		*REAR BUMPER	Not Necessary	2,333.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	182.00 FL	*- FL
10	1		*REAR SHOCK ABSORBER LH	Not Necessary	674.20 FL	*- FL
11	1		*REAR KNUCKLE ARM LH	Not Necessary	930.00 FL	*- FL
12	1		*REAR LOWER ARM LH	Bent	642.00 FL	*642.00 FL
13	1		*REAR WHEEL HUB BEARING	Damaged	450.00 FL	*450.00 FL
14	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
15	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*REAR RIM LH	Cut	1,000.00 FS	*750.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,269.97</b>	<b>4,433.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,135.97	320.30
<b>Total Parts (\$\$)</b>	<b>12,134.00</b>	<b>4,112.70</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
2	TO TRANSFER 1/4 GLASS FROM OLD DOOR TO NEW	New	250.00	40.00
3	TO TRANSFER OLD DOOR ATTACHMENT TO NEW	New	200.00	40.00
4	WHEEL ALIGNMENT	New	150.00	80.00
5	TO REMOVE AND REFIT UNDERCARRIAGE ITEMS	New	250.00	180.00
6	PANEL BEATING ON AFFECTED AREA	New	1,500.00	600.00
7	CUSTOMIZED WRAPPING	New	2,500.00	250.00
8	APPLY ANTI RUST ON AFFECTED AREA	New	100.00	50.00
9	SPRAY PAINTING	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,050.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >