

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010828/T1QF3Q2

Date: 10/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00051832001
Claimant Vehicle No :	SJR6222Z	Insured Vehicle No :	SGV6646Z
Date of Loss:	02/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203717/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6222Z	Engine No:	PE31070818
Make & Model:	MAZDA BIANTE, 2.0 (A)	Chassis No:	JM6CC1071H0111224
Reg. Date:	17/07/2017 (Man. Year: 2017)	Odometer:	78401 km
Colour:	Bronze		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,869.50	6,616.20	253.30	3.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	4,580.00	2,470.00	35.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,919.50	11,196.20	2,723.30	19.56
+ GST 7.00/7.00% (\$\$)	974.37	783.73	190.64	19.57
Nett Amount (\$\$)	14,893.87	11,979.93	2,913.94	19.56

INSPECTION

Date of Assignment:	08/10/2020	
Date Inspected:	09/10/2020 Inspected At:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
		27A Tanjong Penjuru
		Singapore 609042
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2020)
Parts:	M1-MPV	MAZDA BIANTE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR6222Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,170.50 FS	*1,170.50 FS
2	2		*GROMMET,REAR BUMPER	Necessary	9.40 FS	*9.40 FS
3	2		*PIN LOCATOR,REAR BUMPER	Necessary	8.40 FS	*8.40 FS
4	2		*GROMMET,REAR BUMPER	Necessary	6.40 FS	*6.40 FS
5	2		*RIVET,REAR BUMPER	Necessary	7.60 FS	*7.60 FS
6	2		*FASTENER,REAR BUMPER	Necessary	6.40 FS	*6.40 FS
7	1		*STRIPE LHS,REAR BUMPER	Necessary	86.00 FS	*86.00 FS
8	1		*STRIPE RHS,REAR BUMPER	Necessary	86.00 FS	*86.00 FS
9	1		*STRIPE CENTER,REAR BUMPER	Necessary	130.10 FS	*130.10 FS
10	1		*REFLECTOR RHS,REAR BUMPER	Not Necessary	124.50 FS	*- FS
11	1		*RETAINER RHS	Not Necessary	48.80 FS	*- FS
12	2		*TAPE PROTECTOR,REAR BUMPER	Necessary	7.00 FS	*7.00 FS
13	1		*TAILGATE	Dented	1,699.70 FS	*1,699.70 FS
14	2		*VALVE ONEWAY,TAILGATE	Necessary	24.00 FS	*24.00 FS
15	1		*FINISHER,TAILGATE	Cut	2,018.60 FS	*2,018.60 FS
16	3		*FINISHER,TAILGATE	Necessary	18.60 FS	*18.60 FS
17	1		*ORNAMENT,SKYACTIV	Necessary	117.10 FS	*117.10 FS
18	1		*FASTENER,REAR WINDSCREEN	Necessary	2.80 FS	*2.80 FS
19	5		*SPACER,REAR WINDSCREEN	Necessary	64.00 FS	*64.00 FS
20	2		*FASTENER,REAR WINDSCREEN	Necessary	16.40 FS	*16.40 FS
21	1		*TAILLAMP RHS	Cracked	1,117.20 FS	*1,117.20 FS
22	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,869.50** **6,616.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	1,650.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	1,890.00	1,260.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
5	TO TRANSFER TAILGATE MECHANISM	New	330.00	0.00
6	TO TRANSFER REVERSE SENSORS (WITH REVERSE SENSOR)	New	660.00	330.00
7	TO TRANSFER REVERSE CAMERA (WITH REVERSE CAMERA)	New	660.00	330.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
9	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$\$)			7,050.00	4,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >