

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20010829/UPS3Q2

Date:

28/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0000102_01

Claimant Vehicle No : SMU986R**Insured Vehicle No :**

PC5399L

Date of Loss: 06/10/2020

Nature of Claim:

TP

Claim No:

MFL2020D0001986

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMU986R**

Make & Model: HYUNDAI ACCENT, 1.4 (A)

Engine No: G4LCKU245392

Reg. Date: 29/07/2020 (Man. Year: 2019)

Chassis No: KMHCU41BTU481815

Colour: White

Odometer: 2729 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,974.52	3,637.06	2,337.46	39.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,000.00	1,480.00	42.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,454.52	5,637.06	3,817.46	40.38
Approved Total (Overridden) (S\$)		4,500.00		

Nett Amount (S\$)	9,454.52	4,500.00	4,954.52	52.40
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		4,860.00		
Liabe Amount (50.00%) (S\$)		2,430.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,466.45		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 08/10/2020

Date Inspected: 08/10/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Zoom Autowerks Pte Ltd
 832 SIMS AVENUE #12-884 EUNOSVILLE
 Singapore 400832

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2021)
Parts:	144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU986R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed /Torn	685.10 FL	*545.32 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	102.40 FL	*- FL
3	1		*REAR BUMPER BRACKET RH	Not Necessary	96.40 FL	*- FL
4	1		*REAR BUMPER SPONGE	Not Necessary	108.30 FL	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
6	1		*REAR TAILLAMP RH	Not Necessary	586.70 FL	*- FL
7	1		*REAR FENDER RH	Badly Dented / Bent	1,405.20 FL	*1,405.20 FL
8	1		*REAR FENDER INNER SHIELD RH	Deformed	214.20 FL	*105.30 FL
9	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*20.00 FL
10	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	246.30 FL	*246.30 FL
11	1		*REAR DOOR RH	Badly Dented	896.10 FL	*896.10 FL
12	1		*REAR DOOR FRAME BLACK STICKER	Necessary	195.40 FL	*195.40 FL
13	1		*REAR DOOR INNER LOCK RH	Twisted / Shorted	294.80 FL	*294.80 FL
14	1		*REAR DOOR OUTER GLASS MOULDING	Not Necessary	196.10 FL	*- FL
15	1		*REAR DOOR POWER WINDOW MOTOR LINKAGE ASSY	Shorted	425.60 FL	*425.60 FL
16	1		*REAR DOOR PLASTIC INSULATOR SHEET	Not Necessary	68.40 FL	*- FL
17	1		*REAR DOOR INNER TRIMBOARD	Not Necessary	586.10 FL	*- FL
18	1		*SET REAR DOOR INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*REAR DOOR WEATHERSTRIP	Necessary	124.80 FL	*124.80 FL
20	1		*FRONT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*SET WHEEL CAPS	Cut	485.00 FS	*150.00 FS
23	1		*REAR RH TYRE	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,256.90	4,498.82
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,282.38	861.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$)	5,974.52
						3,637.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR RH AFFECTED ACCIDENT AREAS	New	1,200.00	800.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
5	TO REMOVE & INSTALL FRONT RIGHT DOOR ,REAR RIGHT DOOR TRIM ,GARNISH	New	200.00	60.00
6	TO REMOVE & INSTALL REAR FENDER INNER TRIM,GARNISH	New	200.00	80.00
7	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	150.00	60.00
Gross Labour Cost (\$\$)			3,480.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >