

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010831/KGA3Q2**Date:** 04/03/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800088553
Claimant
Vehicle No : SLM2062Y **Insured Vehicle No :** SMC9320Y
Date of Loss: 05/10/2020 Nature of Claim: TP Claim No: 1493506740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM2062Y**
Make & Model: HONDA STEPWAGON, 1.5 (A) Engine No: L15B3615911
Reg. Date: 23/03/2017 (Man. Year: 2016) Chassis No: RP11014708
Colour: Metallic Grey Odometer: 34265 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Goodyear 3 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 3 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,974.36	2,385.80	1,588.56	39.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,340.00	420.00	23.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,734.36	3,725.80	2,008.56	35.03
+ GST 7.00/7.00% (S\$)	401.41	260.81	140.60	35.03
Nett Amount (S\$)	6,135.77	3,986.61	2,149.16	35.03
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,737.61		

INSPECTION

Date of Assignment: 08/10/2020
Date Inspected: 08/10/2020 Inspected At: Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	988.50 F	*988.50 FL
2	10		*FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
3	1		*FRONT BUMPER CORNER RETAINER LH	Distorted	19.00 F	*19.00 FL
4	1		*FRONT BUMPER SIDE FOG LAMP COVER	Serviceable	155.00 F	*- FL
5	1		*FRONT BUMPER SIDE FOG LAMP COVER CHROME MOULDING	Serviceable	165.00 F	*- FL
6	1		*FRONT WHEEL RIM LH (LOCAL REPAIR)	Dented	687.36 FS	*380.00 FS
7	1		*FRONT SHOCK ABSORBER	Bent	479.00 F	*479.00 FL
8	1		*FRONT KNUCKLE ARM	Bent	502.00 F	*502.00 FL
9	1		*FRONT KNUCKLE ARM BEARING	Necessary	150.50 F	*150.50 FL
10	1		*FRONT KNUCKLE ARM BEARING HUB	Distorted	262.00 F	*262.00 FL
11	1		*FRONT LOWER ARM	Not Necessary	341.00 F	*- FL
12	1		*FRONT TYRE (30%)	Cut	190.00 FS	*57.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,974.36	2,873.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	487.20
Total Parts (\$\$)	3,974.36	2,385.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	250.00	180.00
2	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
3	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
4	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT FENDER ,FRONT DOOR ,ROCKER PANEL SKIRT AND PARTS REPLACEMENT	New	600.00	400.00
5	TO RESPRAY AFFECTED AREAS	New	750.00	680.00
			Gross Labour Cost (\$)	1,760.00
				1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >