



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 2897E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT R/H DOOR (CONSISTENT)	DENTED	981.45	981.45
1	FRONT R/H DOOR OUTER HANDLE (CONSISTENT)	CUT	154.40	154.40
1	FRONT R/H DOOR OUTER CENTER GARNISH (CONSISTENT)	CUT	125.60	125.60
1	FRONT R/H DOOR INNER LOCK (CONSISTENT)	DAMAGED	455.40	298.00
1	FRONT R/H DOOR RUBBER (CONSISTENT)	NOT NECESSARY	201.10	-
1	FRONT R/H DOOR GLASS GEAR MOTOR ASSY (CONSISTENT)	NOT NECESSARY	385.80	-
1	REAR R/H DOOR (CONSISTENT)	DENTED	981.45	981.45
1	REAR R/H DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	154.40	-
1	REAR R/H DOOR OUTER CENTER GARNISH (CONSISTENT)	CUT	125.60	125.60
1	REAR R/H DOOR INNER LOCK (CONSISTENT)	NOT NECESSARY	455.40	-
1	REAR R/H DOOR RUBBER (CONSISTENT)	NOT NECESSARY	201.10	-
1	REAR R/H DOOR GLASS GEAR MOTOR ASSY (CONSISTENT)	DAMAGED	385.80	385.80
1	REAR R/H FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	981.75	-
1	REAR BUMPER (CONSISTENT)	TORN	391.40	391.40
1	REAR R/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	121.25	35.00
1	REAR R/H TAIL LAMP (CONSISTENT)	NOT NECESSARY	281.45	-
1	REAR R/H RIM (CONSISTENT)	NOT NECESSARY	550.00	-
	LESS 25% DISCOUNT		-	-869.68
			6,933.35	2,609.02
<u>SPECIAL NETT ITEMS</u>				
1	CUSTOMIZED CHROME WRAP (CONSISTENT) (SN)	NECESSARY	1,500.00	1,200.00
			1,500.00	1,200.00
<u>LABOUR</u>				
	TO REMOVE & REFIT CUSTOMIZED CHROME WRAP .		600.00	300.00
	TO REMOVE & REFIT FRONT DOOR GLASS MOTOR GEAR MOTOR .		200.00	80.00
	TO REMOVE & REFIT REAR DOOR GLASS MOTOR GEAR MOTOR .		200.00	80.00

Report Ref No. CC4/ASM20010835/Abs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT CUSHION .	NOT NECESSARY	200.00	-
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR R/H FENDER.		1,200.00	600.00
	SPRAY PAINTING .		1,200.00	800.00
			3,600.00	1,860.00
GRAND TOTAL			12,033.35	5,669.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/ASM20010835/Abs3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.