

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010839/KRS3Q2
Date: 19/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900019366
Claimant Vehicle No :	GBE8790A	Insured Vehicle No :	SMJ2534G
Date of Loss:	06/10/2020	Nature of Claim:	TP
		Claim No:	4331840136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8790A		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2598295
Reg. Date:	22/04/2016 (Man. Year: 2016)	Chassis No:	JTFHT02P400192244
Colour:	White	Odometer:	177342 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,070.49	4,195.11	875.38	17.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	3,160.00	950.00	23.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,180.49	7,355.11	1,825.38	19.88
Approved Total (Overridden) (S\$)		5,850.00		

(S\$)	9,180.49	5,850.00	3,330.49	36.28
+ GST 7.00/7.00% (S\$)	642.63	409.50	233.13	36.28
Nett Amount (S\$)	9,823.12	6,259.50	3,563.62	36.28
+ Loss of Use (10.0 x S\$80.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		7,067.50		

INSPECTION

Date of Assignment: 08/10/2020

Date Inspected: 08/10/2020

Estimated Period of Repair: 9.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	373.02 FL	*373.02 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Cracked	27.90 FL	*27.90 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*REAR TAILGATE	Bent	2,162.00 FL	*2,162.00 FL
5	1		*TAILGATE LOGO	Necessary	66.78 FL	*66.78 FL
6	1		*TAILGATE INNER LOCK	Jammed	249.62 FL	*249.62 FL
7	1		*TAILGATE INNER RUBBER (50%)	Cut	276.68 FS	*184.45 FS
8	1		*RH TAILLAMP	Cracked	256.90 FL	*256.90 FL
9	1		*RH TAILLAMP LOWER GARNISH	Bent	84.60 FL	*84.60 FL
10	1		*REAR END PANEL OUTE	Bent	349.80 FL	*349.80 FL
11	1		*REAR END PANEL INNER	Repair	1,044.20 FL	*- FL
12	1		*REAR RH SIDE PANEL	Bent / Warped	1,062.60 FL	*1,062.60 FL
13	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
14	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
15	1		*TAILGATE INNER PROTECTOR	Necessary	280.00 FS	*280.00 FS
					Sub Total (\$\$)	6,495.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,424.61
					Total Parts (\$\$)	5,070.49

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE & ATTACHMENT ,LOCK ASSY ,RH SLIDING DOOR & TRUCK ASSY ,CUT ,WELD & RENEW ,REAR END PANEL REAR RH SIDE PANEL ,KNOCK & REPAIR REAR END PANEL ,REAR FLOOR BOARD PANEL ,REAR RH FENDER INNER PANEL & REALIGN THE SAME	New	1,500.00	1,300.00
3	REMOVE & REFIX REAR CARGO CANOPY	New	800.00	300.00
4	PUTTY & RESPRAY ON REAR RH SIDE PANEL ,REAR FLOORBOARD PANEL ,REAR END PANEL ,TAILGATE & ALL AFFECTED AREAS	New	1,000.00	900.00
5	TO REWRITE ADVERTISEMENT	New	600.00	450.00
6	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (\$\$)			4,110.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >