

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/A1620010845/U903

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMH 852L

at Workshop m/s

ECO Automobile

of

Insured:

SMR 7423T

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

873k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA 35920

Vehicle: IN / OUT

Date:

Person Contacted:

Rep. Pl.

Date / Time

Action / Instruction

OI said slight damage.

16/10/20 1/5 # 4500 confirmed w. the Repairer

Veh No:

SMH 852L

Yr Regn:

1119

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Shuttle Hybrid 1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

178927

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP 72000909

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/10/20

D.O.I.

8/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) \$ + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

)

TOTAL

Not Authorized
dhr
8/10/20
4500/
d/sa 5 days.



VEHICLE NO. SMH852L HONDA SHUTTLE DOA 07/10/20

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Tailgate <i>Body</i>		1425.00	✓ 1193.40
1	Tailgate centre chrome garnish <i>12X</i>		425.00	X
1set	Tailgate centre chrome garnish clips <i>12X</i>		40.00	X
2	Tailgate top hinges @94.20 <i>12X</i>		188.40	X
1	Tailgate inner lock <i>7mm</i>		278.00	✓ 155.20
1	Tailgate lock actuator <i>12X</i>		248.00	X
1	Tailgate inner trim board <i>Refers</i>		482.00	✓
2	Tailgate damper @298.20 <i>12X</i>		596.40	X
2	Tailgate rubber stopper @5.80 <i>12X</i>		11.60	X
1	Tailgate Honda badge <i>12X</i>		92.00	✓ 37.40
1	Tailgate SHUTTLE emblem <i>12X</i>		98.00	✓ 60.00
1	Tailgate Hybrid Emblem <i>12X</i>		92.00	✓ 68.00
2	Tailgate reflectors @395.00 <i>12X</i>		790.00	X
1	Tailgate wiper motor <i>12X</i>		492.00	X
1	Rear floor panel <i>2X</i>		1250.00	X
1	Rear floor panel top board <i>12X</i>		298.00	X
1	Rear floor panel inner tool tray <i>12X</i>		238.00	X
2	Rear side tool trays @142 <i>12X</i>		284.00	X
1	Rear windscreen <i>12X</i>		1250.00	X
1	Rear windscreen moulding <i>12X</i>		172.00	✓
2	RHS & LHS Rear fender @782.50 <i>12X</i>		1565.00	X
2	RHS & LHS Rear fender inner side trim @224 <i>12X</i>		448.00	X
2	RHS & LHS Rear fender inner splash shield <i>12X</i>		198.00	X
1	Rear bumper <i>De/warp</i>		1242.00	✓ 1180.60
2	Rear bumper side retainers @144.00 <i>12X</i>		288.00	X
2	Rear bumper reflectors @152.00 <i>12X</i>		304.00	X
2	Rera bumper reflectors cover @78.20 <i>12X</i>		156.40	X
1	Rear bumper inner foam <i>70-1</i>		42.00	✓
2	RHS & LHS Taillamps @984.50 <i>12X</i>		1969.00	X
1	Rear end panel <i>70</i>		982.00	✓ 631.20
1	Rear end panel top garnish <i>De/7mm</i>		261.00	✓ 168.20
1	Rear boot edge weatherstrip <i>7mm</i>		184.00	✓
	PARTS C/F		16389.80	

1-4343-4
2026
347472

VEHICLE NO. SMH852L HONDA SHUTTLE DOA 07/10/20

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	16389.80	
			16389.80	
		less 20%	3277.96	20%
	<u>SPECIAL NETT ITEMS</u>		13111.84	
1 set	Rear Bumper clips		RM 60.00	50
1	Rear windscreen sealant		RM 100.00	40
1 set	Reverse sensor		shubd 280.00	200
1	Reverse camera		RM 380.00	X
1 set	Tailgate inner trim clips		RM 60.00	X
1	Rear end panel sealant		RM 100.00	50
1	Rear floor panel sealant		RM 100.00	X
1	Tailgate wiper blade		RM 72.00	X
1	Rear licence plate w/holder		RM 75.00	X
2	Rear licence plate lamps @49.50		RM 99.00	X
		TOTAL PARTS	14437.84	

VEHICLE NO. SMH852L HONDA SHUTTLE DOA 31/03/20

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1400.00	900
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00	20
4	To remove and replace/refix ar trims, garnish and fittings so as to facilitate replairs at rear	250.00	80
5	To remove and replace rear windscreen	140.00	120
6	To remove and replace reverse sensors and check for proper function	150.00	50
7	To remove and replace reverse camera and check for proper function	150.00	
8	To provide anti-rust treatment on affected areas	270.00	60
	Labour Total :	4360.00	
	TOTAL (PARTS & LABOUR):	18797.84	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 347472
 S.W - 340.00
 1 - 1830.00
 564472
 204
 4415.