

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20010847/UBA3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	D20MPC0005293
Claimant		
Vehicle No : FX1181G	Insured Vehicle No :	SJY7640G
Date of Loss: 19/09/2020	Nature of Claim: TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX1181G	Engine No:	NF125MDE0067429
Make & Model:	HONGSHI NF125MD, 125cc	Chassis No:	NF125MD0067429
Reg. Date:	30/08/2003 (Man. Year: 2003)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,899.00	2,357.50	2,541.50	51.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	335.00	215.00	39.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,449.00	2,692.50	2,756.50	50.59
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	5,449.00	2,100.00	3,349.00	61.46
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	08/10/2020	
Date Inspected:	08/10/2020 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT)
		1 KAKI BUKIT AVE 6 #02-62
		Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Nov 2020)	
Parts:	N/A	HONGSHI NF125MD 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX1181G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Bent/Twisted	280.00 FL	*280.00 FL
2	2		*FORK OUTER TUBES	Bent/Twisted	290.00 FL	*290.00 FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
4	1		*SIDE MIRROR O/S	Cut	48.00 FL	*48.00 FL
5	2		*FRONT SIGNALS (1 SET)	Cracked	70.00 FL	*70.00 FL
6	1		*HEADLAMP ASSY	Cracked	60.00 FL	*60.00 FL
7	1		*METER ASSY	Not Necessary	360.00 FL	*- FL
8	1		*HANDLE-BAR	Serviceable	80.00 FL	*- FL
9	1		*HANDLE-BAR BRACKET	Not Necessary	95.00 FL	*- FL
10	1		*HAND GRIP (1 SET)	Cut	25.00 FL	*25.00 FL
11	1		*BRAKE LEVER	Cracked	20.00 FL	*20.00 FL
12	1		*FRONT BRAKE DISC	Not Necessary	80.00 FL	*- FL
13	1		*FRONT RIM	Repair	260.00 FL	*- FL
14	1		*FRONT RIM SHAFT	Not Necessary	35.00 FL	*- FL
15	1		*FRONT FOOTREST BRACKET	Bent	55.00 FL	*55.00 FL
16	1		*FRONT FOOTREST RUBBERS	Torn	56.00 FL	*56.00 FL
17	1		*FEAR PEDAL	Not Necessary	40.00 FL	*- FL
18	1		*BRAKE PEDAL	Cut	42.00 FL	*42.00 FL
19	1		*REAR FOOTREST	Cut	38.00 FL	*38.00 FL
20	1		*REAR FOOTREST BRACKET	Not Necessary	50.00 FL	*- FL
21	1		*EXHAUST ASSY	Not Necessary	425.00 FL	*- FL
22	1		*EXHAUST PIPE COVER	Not Necessary	310.00 FL	*- FL
23	1		*FRONT FENDER	Cracked	68.00 FL	*68.00 FL
24	1		*FRONT INNER COVER CENTRE	Cracked	45.00 FL	*45.00 FL
25	1		*FRT-REAR FENDER	Cracked	68.00 FL	*68.00 FL
26	1		*REAR SWING ARM	Repair	220.00 FL	*- FL
27	1		*FAIRING ASSY (1 SET)	Cracked	485.00 FL	*485.00 FL
28	1		*REAR RIM	Cut	290.00 FL	*290.00 FL
29	1		*REAR RIM SHAFT	Repair	40.00 FL	*- FL
30	1		*REAR SUSPENSION (1 SET)	Not Necessary	320.00 FL	*- FL
31	1		*CHAIN ADJUST	Bent	30.00 FL	*30.00 FL
32	1		*BASKET	Cracked	30.00 FL	*30.00 FL
33	1		*SIDE STAND	Not Necessary	40.00 FL	*- FL
34	1		*MAIN STAND	Not Necessary	60.00 FL	*- FL
35	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
36	1		*NUMBER PLATE (1 SET)	Bent	28.00 FS	*10.00 FS
37	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
38	1		*STEERING CONE BEARING (1 SET)	Necessary	85.00 FS	*85.00 FS
39	1		*REAR BOX	Cut	200.00 FS	*150.00 FS
40	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
41	1		*STICKER SET	Necessary	60.00 FS	*60.00 FS
42	1		*E.R.P IU	Repair	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **5,359.00** **2,576.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (\$)					460.00	218.50
Total Parts (\$)					4,899.00	2,357.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	300.00
Gross Labour Cost (\$\$)			550.00	335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >