

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20010851/UGA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SMH552C	Insured Vehicle No :	GBK1682T
Date of Loss:	08/10/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002007

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH552C		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B1445343
Reg. Date:	09/01/2019 (Man. Year: 2018)	Chassis No:	GK31337891
Colour:	Silver	Odometer:	24389 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,578.10	13,000.16	13,577.94	51.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,340.00	4,870.00	3,470.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,918.10	17,870.16	17,047.94	48.82
Approved Total (Overridden) (\$\$)		14,200.00		
Nett Amount (\$\$)	34,918.10	14,200.00	20,718.10	59.33
+ Car Rental (8.0 x S\$100.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		120.00		
Nett Liability (\$\$)		15,127.45		

INSPECTION

Date of Assignment:	08/10/2020	
Date Inspected:	08/10/2020	Inspected At: Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	15.0 days	

2/16/2021

Adjuster Report

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH552C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,422.30 F	*1,150.20 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	68.10 F	*68.10 FL
3	1		*TAILGATE	Badly Dented	845.20 F	*845.20 FL
4	1		*TAILGATE OUTER GARNISH	Broken	355.40 F	*245.50 FL
5	1		*TAILGATE OUTER OPENER SWITCH	Damaged	255.20 F	*220.20 FL
6	1		*TAILGATE H LOGO	Necessary	35.00 F	*35.00 FL
7	1		*TAILGATE FIT EMBLEM	Necessary	38.00 F	*38.00 FL
8	1		*TAILGATE REAR WIPER ARM	Bent	188.60 F	*188.60 FL
9	1		*TAILGATE WIPER BLADE	Damaged	65.50 F	*65.50 FL
10	1		*TAILGATE WIPER MOTOR	Bent / Twisted	485.20 F	*485.20 FL
11	2		*TAILGATE LICENCE PLATE LAMPS	Not Necessary	170.00 F	*- FL
12	2		*TAILGATE REFLECTORS	Cracked	562.00 F	*332.40 FL
13	1		*TAILGATE INNER LOCK	Twisted / Jammed	209.20 F	*145.20 FL
14	1		*TAILGATE INNER TRIM BOARD	Distorted / Cracked	388.20 F	*322.50 FL
15	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
16	1		*TAILGATE INNER PULL GARNISH	Not Necessary	35.00 F	*- FL
17	1		*TAILGATE WEATHERSTRIP	Twisted	166.80 F	*166.80 FL
18	1		*ROOF LINING	Warped	1,280.00 F	*1,280.00 FL
19	1		*REAR BUMPER	Distorted	645.50 F	*492.70 FL
20	1		*REAR BUMPER LOWER CENTRE BLACK GARNISH	Distorted	115.00 F	*115.00 FL
21	2		*REAR BUMPER LOWER SIDE BLACK GARNISHS	Cracked	130.00 F	*130.00 FL
22	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked	45.00 F	*22.50 FL
23	1		*REAR BUMPER SPLASH SHIELD N/S	Torn	88.20 F	*88.20 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
25	1		*REAR BUZZLE SENSOR	Cracked	350.00 F	*350.00 FL
26	1		*REAR ANTENNA SENSOR	Cracked	320.00 F	*215.40 FL
27	2		*TAILLAMPS	N/S Broken / O/S Cracked	900.40 F	*761.00 FL
28	2		*TAILLAMP HOUSING PANELS	Badly Dented	850.00 F	*630.00 FL
29	1		*REAR END PANEL	Badly Dented	366.00 F	*328.00 FL
30	1		*REAR END PANEL TOP GARNISH	Distorted	198.00 F	*198.00 FL
31	1		*REAR FLOOR PANEL	Crumpled / Buckled	945.20 F	*945.20 FL
32	1		*REAR FLOOR PANEL TOP BOARD	Warped	365.00 F	*365.00 FL
33	1		*REAR FLOOR TOOLS SPONGE	Torn	680.00 F	*548.20 FL
34	1		*REAR FENDER INNER TOP GARNISH N/S	Cracked	145.20 F	*145.20 FL
35	1		*REAR FENDER INNER WHEEL HOUSING PANEL N/S	Badly Dented	988.20 F	*845.20 FL
36	1		*REAR FENDERS	N/S Distorted / O/S Repair	1,942.00 F	*971.00 FL
37	1		*REAR FENDER INNER TRIMS	N/S Deformed	730.00 F	*365.00 FL
38	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 F	*- FL
39	2		*REAR FENDER GLASS	Not Necessary	598.00 F	*- FL
40	2		*REAR DOORS	Repair	1,570.40 F	*- FL
41	1		*REAR DOOR INNER LOCKS	N/S Damaged	533.00 F	*266.50 FL
42	2		*REAR DOOR INNER BOARDS	Not Necessary	576.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR EXHAUST	Repair	645.00 F	*- FL
44	1		*REAR EXHAUST HEAT SHIELD	Bent	185.00 F	*185.00 FL
45	1		*REAR EXHAUST MOUNTING	Not Necessary	35.00 F	*- FL
46	1		*CENTRE EXHAUST PIPE	Repair	942.30 F	*- FL
47	2		*REAR SHOCK ABSORBERS	Serviceable	430.00 F	*- FL
48	1		*REAR WHEEL HUB BEARINGS	N/S Damaged	584.00 F	*292.00 FL
49	1		*REAR AXLE BEAM	Bent / Twisted	1,120.00 F	*980.20 FL
50	2		*REAR AIR VENTS	Not Necessary	70.00 F	*- FL
51	2		*REAR FLOOR INNER SIDE PANELS	Repair	376.00 F	*- FL
52	1		*REAR WINDSCREEN SOLAR FILM	Necessary	280.00 FS	*200.00 FS
53	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
54	1		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
55	1		*REAR LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
56	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*350.00 FS
57	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
58	1		*REAR FENDER GLASS SEALANT N/S	Necessary	80.00 FS	*30.00 FS
59	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
60	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	280.00 FS	*150.00 FS
61	1		*SET REAR SEAT FRAME BRACKET	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,578.10	15,977.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,977.54
Total Parts (\$\$)	26,578.10	13,000.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	100.00
5	TO DISMANTLE & REPLACED REAR EXHAUST	New	150.00	60.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
7	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	New	380.00	250.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
9	TO DISMANTLE & REFIX REAR FENDER GLASS LH/RH	New	150.00	60.00
10	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
11	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
12	TO SPRAY RUST PROOFING	New	200.00	120.00
13	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,800.00	2,400.00
14	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,500.00
Gross Labour Cost (S\$)			8,340.00	4,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >