



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2106974

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/10/2021
Reference CC4/FCI20010852/Ges3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJV 7534X
Insured Veh. SHA 8660S
Claim No. D20004053MFSH
Policy No. D-20094921MFSH
Accident Date 03/10/2020
Inspection Date 08/10/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010852/Ges3q2 Date: 07/10/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8660S	Veh. Inspected	SVJ 7534X	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20004053MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	08/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053HY9305142491	Colour	BLACK	
Odometer	133724 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	8 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/10/2020	Inspection Date	08/10/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7534X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT	798.40	469.55
1	BONNET LOCK	NOT NECESSARY	295.20	-
2	BONNET HINGE LHS & RHS @\$195.20	BENT	390.40	60.80
1	BONNET OUTER SEAL	MISSING	128.70	54.00
1	BONNET INSULATOR	NOT NECESSARY	225.70	-
1	FRONT BUMPER	DEFORMED	721.40	399.60
1	FRONT BUMPER REINFORCEMENT	BENT	499.20	312.30
1	LHS FRONT BUMPER RETAINER	NOT NECESSARY	128.50	-
1	RHS FRONT BUMPER RETAINER	DEFORMED	128.50	63.40
1	FRONT BUMPER GRILLE	DEFORMED	598.70	285.20
1	FRONT BUMPER LOGO	NECESSARY	120.50	58.20
1	FRONT BUMPER LOWER GRILLE	DEFORMED	315.20	69.60
1	LHS FRONT BUMPER SIDE GRILLE	NOT NECESSARY	89.70	-
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	187.90	-
1	RHS FRONT FOG LIGHT GARNISH	BROKEN	87.60	65.00
1	LHS FRONT FOG LIGHT GARNISH	NOT NECESSARY	87.60	-
1	LHS HEADLIGHT	BROKEN	602.80	425.00
1	LHS HEADLIGHT SUPPORT PANEL	BUCKLED	187.90	95.00
1	RHS HEADLIGHT	BROKEN	602.80	425.00
1	RHS HEADLIGHT SUPPORT PANEL	BUCKLED	187.90	95.00
1	FRONT SUPPORT PANEL	BUCKLED	684.50	545.20
1	FRONT SUPPORT PANEL TOP GARNISH	CUT	97.60	90.00
1	AIRCON CONDENSER	BENT	984.50	984.50
1	RADIATOR	BENT	754.80	754.80
1	RADIATOR TOP GARNISH	DEFORMED	269.70	269.70
1	LHS FRONT FENDER	TO REPAIR SEE LABOUR	896.90	-
1	LHS FRONT FENDER SHIELD	NOT NECESSARY	99.90	-
1	LHS FRONT FENDER INNER TRIM	NOT NECESSARY	336.70	-
1	LHS FRONT FENDER INNER AIR VENT	NOT NECESSARY	184.70	-
1	RHS FRONT FENDER	BUCKLED	896.90	388.50

Report Ref No. CC4/FCI20010852/Ges3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHS FRONT FENDER EMBLEM 'VVTI'	NECESSARY	87.40	45.00
1	RHS FRONT FENDER SHIELD	TORN	99.90	99.90
1	RHS FRONT FENDER INNER TRIM	NOT NECESSARY	336.70	-
1	RHS FRONT FENDER INNER AIR VENT	NOT NECESSARY	184.70	-
1	RHS FRONT KNUCKLE ARM	NOT NECESSARY	447.93	-
1	RHS FRONT WHEEL BEARING	NOT NECESSARY	116.70	-
1	RHS FRONT LOWER ARM	NOT NECESSARY	427.57	-
1	REAR BUMPER	DEFORMED	784.20	427.00
1	RHS REAR BUMPER RETAINER	CUT	79.20	79.20
1	WIPER GARNISH RH	MISSING	145.20	56.50
1	WIPER GARNISH CENTER	CRACKED	215.60	200.00
2	CHASSIS BRACKET	O/S BENT / N/S NOT NECESSARY	423.80	211.90
1	WIPER TANK	DEFORMED	185.30	101.20
1	RADIATOR TOP HOSE	CUT	245.20	88.60
1	RADIATOR SIDE GARNISH	CRACKED	212.50	38.20
1	LHS REAR BUMPER RETAINER	NOT NECESSARY	79.20	-
1	RHS REAR BUMPER BRACKET	NOT NECESSARY	89.70	-
1	LHS REAR BUMPER BRACKET	NOT NECESSARY	89.70	-
1	RHS REAR BUMPER REFLECTOR	BROKEN	178.40	90.00
1	BOOT	TO REPAIR SEE LABOUR	791.20	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	182.35	-
1	BOOT EMBLEM 'VIOS'	NECESSARY	72.90	45.00
1	BOOT EMBLEM 'E'	NECESSARY	62.30	34.37
1	BOOT LOCK	JAMMED	71.10	71.10
1	END PANEL	TO REPAIR SEE LABOUR	781.90	-
1	END PANEL TOP GARNISH	DEFORMED	374.45	235.00
1	RHS TAIL LAMP	CRACKED	481.90	310.00
1	RHS TAIL LAMP PANEL	NOT NECESSARY	371.50	-
1	SPARE TYRE COMPARTMENT	NOT NECESSARY	975.10	-
1	SPARE TYRE COMPARTMENT BOARD	NOT NECESSARY	371.24	-
1	EXHAUST MUFFER	NOT NECESSARY	681.30	-

Report Ref No. CC4/FCI20010852/Ges3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST MUFFER HEAT SHIELD	NOT NECESSARY	192.40	-
2	REINFORCEMENT BRACKET	BENT	201.76	58.90
	LESS 25% DISCOUNT		-5,407.78	-2,025.56
			16,223.32	6,076.66
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIP @\$5.00 (SN)	NECESSARY	50.00	20.00
10	RHS FRONT FENDER SHIELD CLIP @\$5.00 (SN)	NECESSARY	50.00	20.00
10	LHS FRONT FENDER SHIELD CLIP @\$5.00 (SN)	NOT NECESSARY	50.00	-
10	BONNET INSUALTOR CLIP @\$5.00 (SN)	NOT NECESSARY	50.00	-
1	FRONT BUMPER NO .PLATE WITH CAING (SN)	NECESSARY	50.00	40.00
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	20.00
1	END PANEL TOP GARNISH CLIP (SN)	NECESSARY	5.00	5.00
1	REAR NO.PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	85.00	30.00
			820.00	335.00
	<u>LABOUR</u>			
	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS .INCLUSIVE OF THE REPAIR OF LHS FRONT FENDER ,BOOT AND END PANEL .		2,500.00	1,400.00
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHE ACCIDENT AFFECTED AREAS .		1,800.00	1,600.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.}		50.00	40.00
	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED.}		50.00	-
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR .	NOT NECESSARY	80.00	-
	TO CHECK WIRING AND LIGHTING SYSTEM.		80.00	30.00
	RE-ADJUST WHEEL ALIGNMENT.		100.00	60.00
	TO REMOVE AND FIT FRONT UNDERCARRIAGE .	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REVERSE SENSOR .		80.00	40.00
	TO REMOVE AND REFIT REAR TRIM GARNISH ASSY .		250.00	60.00

Report Ref No. CC4/FCI20010852/Ges3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT AIRCON CONDENSER ,RADIATOR ASSY .}		250.00	120.00
	TO TOP UP 134a REFRIGERANT.}		150.00	-
			5,540.00	3,350.00
GRAND TOTAL			22,583.32	9,761.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,800.00

Report Ref No. CC4/FCI20010852/Ges3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 7534X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 7534X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

