

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3566D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	IONIQVC COVER-RR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	IONIQVC PANEL ASSY-QUARTE	TO REPAIR SEE LABOUR	1,768.30	-
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	IONIQV1&3 CAP ASSY-WHEEL	CUT	346.40	346.40
	LESS 20% DISCOUNT		-519.22	-69.28
			2,076.88	277.12
<u>NETT ITEMS</u>				
2	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-8.00	-8.00
			72.00	72.00
<u>SPECIAL NETT ITEMS</u>				
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF IONIQVC COVER-RR BUMPER AND IONIQVC PANEL ASSY-QUARTE.		1,000.00	480.00
	SPRAYPAINT CHARGE.		800.00	600.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE / REFIX UPHOLSTERY ASST REPAIR.	NOT NECESSARY	100.00	-
	REMOVE / REFIX REVERSE SENSOR ASSY.	NOT NECESSARY	80.00	-
			-	-
			-	-
			2,080.00	1,110.00
GRAND TOTAL			4,278.88	1,509.12
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,509.12

Report Ref No. NS/INC20010854/Eqf3e2

A stylized, handwritten signature in black ink, consisting of several fluid, overlapping strokes.

CHEN TSUE YEE

Automotive Assessor

A stylized, handwritten signature in black ink, featuring a large, looped initial 'L' followed by a smaller 'h'.

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.