

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010871/ATF3E2

Date: 23/03/2021

REFERENCE

Insured/Claimant:	CHIU ALLEN S	Policy No:	1800088553		
Date of Loss:	05/10/2020	Nature of Claim:	OD	Claim No:	1493506740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9320Y		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	CVK063249
Reg. Date:	27/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF56JA106384
Colour:	White	Odometer:	39626 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,893.00	9,995.36	9,897.64	49.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,252.00	3,102.00	1,150.00	27.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,145.00	13,097.36	11,047.64	45.76
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	23,345.00	12,297.36	11,047.64	47.32
+ GST 7.00/7.00% (S\$)	1,634.15	860.82	773.33	47.32
Nett Amount (S\$)	24,979.15	13,158.18	11,820.97	47.32

INSPECTION

Date of Assignment:	08/10/2020		
Date Inspected:	08/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Damaged	225.00 FS	*180.00 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	529.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	2,300.00 FS	*- FS
8	2		*ULTRASOUND SENSOR SUPPORT - LH / RH	Not Necessary	102.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	187.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	468.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	242.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	36.00 FS	*28.48 FS
16	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
17	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
18	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
20	1		*HORN - RH LOW TONE	Not Necessary	124.00 FS	*- FS
21	1		*SPRING SHACKLE - RH	Not Necessary	29.00 FS	*- FS
22	1		*FRONT FENDER - RH	Buckled	1,048.00 FS	*838.40 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	73.00 FS	*58.40 FS
25	1		*FRONT FENDER BRACKET - RH	Bent	35.00 FS	*27.60 FS
26	1		*FRONT FENDER MIDDLE BRACKET	Not Necessary	35.00 FS	*- FS
27	1		*FRONT FENDER BRACE - RH	Bent	117.00 FS	*93.60 FS
28	1		*DEFORMATION ELEMENT BRACKET - RH	Not Necessary	49.00 FS	*- FS
29	1		*WHEEL HOUSING LINER - RH	Torn	272.00 FS	*217.20 FS
30	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
31	1		*WHEEL SPOILER	Cracked	73.00 FS	*57.76 FS
32	1		*WHEEL SPOILER TRIM	Not Necessary	36.00 FS	*- FS
33	1		*STONE CHIP GUARD - RH	Necessary	50.00 FS	*39.92 FS
34	1		*FRONT FENDER TRIM - RH	Necessary	157.00 FS	*125.60 FS
35	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	1,012.00 FS	*- FS
36	1		*FENDER LEDGE COVER - INNER	Not Necessary	16.00 FS	*- FS
37	1		*FENDER LEDGE COVER - OUTER	Not Necessary	35.00 FS	*- FS
38	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
39	1		*SUNDRIES	Necessary	250.00 FS	*12.80 FS
40	1		*HEADLIGHTS	Cut	7,812.00 F	*6,249.60 F
41	1		*HEADLIGHTS LIFT CYLINDER-RH	Cracked	196.00 F	*156.80 F
42	1		*HEADLIGHTS LIFT CYLINDER BRACKET-RH	Not Necessary	15.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 19,893.00 9,995.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER. RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,500.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,650.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
Gross Labour Cost (\$\$)			4,252.00	3,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >