

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20010875/ESD3E2

**Date:** 02/11/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS008817

**Claimant Vehicle No :** SHB2533K

**Insured Vehicle No :** GBG3478A

Date of Loss: 08/10/2020

Nature of Claim: TP

Claim No: M2004970

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB2533K**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU390381

Reg. Date: 06/08/2020 (Man. Year: 2019)

Chassis No: KMHCB851CVLU184415

Colour: Yellow

Odometer: 18265 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition: Average

### CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Firestone 5 mm

Rear Left Side: Firestone 5 mm

Front Right Side: Firestone 5 mm

Rear Right Side: Firestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,665.08	2,383.40	1,281.68	34.97
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,300.00	1,090.00	210.00	16.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,976.08</b>	<b>3,484.40</b>	<b>1,491.68</b>	<b>29.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>348.33</b>	<b>243.91</b>	<b>104.42</b>	<b>29.98</b>
<b>Nett Amount (S\$)</b>	<b>5,324.41</b>	<b>3,728.31</b>	<b>1,596.10</b>	<b>29.98</b>

### INSPECTION

Date of Assignment: 08/10/2020 Present Location:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

Date Inspected: 08/10/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB2533K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Broken	418.30 FL	-	*418.30 FL
2	1		*FRT FENDER RH	Dented	490.70 FL	-	*490.70 FL
3	1		*HEADLAMP ASSY RH	Cut	1,993.65 FL	-	*1,993.65 FL
4	1		*FRT BUMPER SIDE BRACKET RH	Broken	35.00 FL	-	*28.00 FL
5	1		*FRT BUMPER SIDE GRILLE RH	Not Necessary	186.00 FL	-	*- FL
6	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
<b>Supplementary #1</b>							
7	1		*RADIATOR GRILLE	Not Necessary	1,409.10 FL	-	*- FL
8	1		*FRT FENDER RH EMBLEM	Necessary	26.60 FL	-	*26.60 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,581.35</b>	<b>2,979.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	916.27	595.85
<b>Total Parts (\$\$)</b>	<b>3,665.08</b>	<b>2,383.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	640.00
2	SPRAYPAINT	New	500.00	400.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,300.00</b>	<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >