



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2103705

INV Date 26/05/2021

Reference CC6/FCI20010882/Aea3q2

Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SML 992U

Insured Veh. SHC 1456B

Claim No. D20004090MFSH

Policy No. D-18088937MFSH

Accident Date 06/10/2020

Inspection Date 08/10/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20010882/Aea3q2	
			Date: 26/05/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SHC 1456B	<b>Veh. Inspected</b>	SML 992U
	<b>Policy No.</b>	D-18088937MFSH	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	D20004090MFSH	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	CHRIS LIM	<b>Assign Date</b>	08/10/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MERCEDES BENZ B180	<b>c.c</b>	1595
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
	<b>Chassis No.</b>	WDD2462422J535153	<b>Colour</b>	BLACK
	<b>Odometer</b>	95733 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/45 R17	PETLAS	6 mm
	<b>L/H Front Tyre</b>	225/45 R17	PETLAS	6 mm
	<b>R/H Rear Tyre</b>	225/45 R17	PETLAS	6 mm
	<b>L/H Rear Tyre</b>	225/45 R17	PETLAS	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	06/10/2020	<b>Inspection Date</b>	08/10/2020
	<b>Survey held at</b>	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 992U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	1,654.00	1,458.00
1	REAR BUMPER SIDE RETAINER	NECESSARY	94.50	94.50
1	REAR FENDER	DENTED	1,855.90	1,855.90
1	REAR QUARTER GLASS MOULDING	NECESSARY	155.60	155.60
1	REVERSE SENSOR	DAMAGED	320.00	250.00
1	REVERSE SENSOR RUBBER	NECESSARY	30.00	30.00
1	REVERSE SENSOR HOLDER	NECESSARY	60.00	25.00
	LESS 10% DISCOUNT		-417.00	-386.90
			3,753.00	3,482.10
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	REAR QUARTER GLASS SEALANT (SN)	NECESSARY	100.00	40.00
1	WHEEL TYRE (SN)	NOT NECESSARY	550.00	-
1	WHEEL RIM (SN)	CUT	1,400.00	650.00
			2,080.00	720.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT ,WELD ,CUT ,KNOCK STRAIGHTEN ,ADJUST GRAZE JOINT.		1,000.00	600.00
	TO PUTTY ,SRPAY PAINT ,POLISH,WAX AFFECTED PARTS AND PANELS .		1,000.00	500.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK .		120.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO.	NOT NECESSARY	180.00	-
			2,650.00	1,240.00
	<b>GRAND TOTAL</b>		<b>8,483.00</b>	<b>5,442.10</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			<b>4,300.00</b>
---	--	--	-----------------

Report Ref No. CC6/FCI20010882/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SML 992U

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

