Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20010884/ATD3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 19/03/2021

REFERENCE

Insured/Claimant: EE CHENG EN SAMUEL Policy No: 2070037067

Date of Loss: 07/10/2020 Nature of Claim: OD Claim No: 1441950853SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS8841H

Make & Model:

AUDI A3 SPORTBACK, 999cc TFSI S TRONIC

Engine No: CHZC38868

(LED) (A)

Reg. Date: 19/03/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V1LA049446

Colour: White Odometer: 8159 km

Engine Capacity: 999 cc

Market Value/New Car S\$120,000.00

Price: 35120,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,586.00	3,883.04	4,702.96	54.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,827.00	4,452.00	5,375.00	54.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,413.00	8,335.04	10,077.96	54.73
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	18,113.00	8,035.04	10,077.96	55.64
+ GST 7.00/7.00% (S\$)	1,267.91	562.45	705.46	55.64
Nett Amount (S\$)	19,380.91	8,597.49	10,783.42	55.64

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 08/10/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*B-PILLAR AND SILL PANEL-LH	Repair	1,971.00 FS	*-FS
2	1		*FRONT DOOR-LH	Distorted	2,267.00 FS	*1,813.60 FS
3	1		*FRONT DOOR OUTER SEAL-LH	Necessary	159.00 FS	*126.80 FS
4	1		*BONDING AGENT	Not Necessary	47.00 FS	*-FS
5	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*-FS
6	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	238.00 FS	*-FS
7	1		*FRONT DOOR CATCH	Not Necessary	104.00 FS	*-FS
8	1		*REAR DOOR-LH	Distorted	2,267.00 FS	*1,813.60 FS
9	1		*REAR DOOR OUTER SEAL-LH	Necessary	159.00 FS	*126.80 FS
10	1		*BONDING AGENT	Not Necessary	47.00 FS	*-FS
11	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*-FS
12	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	127.00 FS	*-FS
13	1		*REAR DOOR CATCH	Not Necessary	93.00 FS	*-FS
14	1		*DOOR HINGE HALF-UPPER PART-LH LOWER	Not Necessary	46.00 FS	*-FS
15	1		*DOOR HINGE HALF-LOWER PART-LH LOWER	Not Necessary	46.00 FS	*-FS
16	1		*WHEEL SPOILER-LH REAR	Not Necessary	35.00 FS	*-FS
17	1		*STONE CHIP	Not Necessary	180.00 FS	*-FS
18	1		*CAVITY WAX	Not Necessary	140.00 FS	*-FS
19	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*-FS
20	1		*SUNDRIES	Necessary	350.00 FS	*2.24 FS
F=Fra	nchise	part. S=Spc	Nett.			
				Total Parts (S\$)	8,586.00	3,883.04

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	560.00
2	TO REMOVE AND REINSTALL LHS FRONT ASSY,ABCD PILLAR TRIMS,SILL TRIMS,FLOOR CARPETS,ELECTRONIC COMPONENTS AND FUSE TRAYS.DISENGAGE LHS SEAT BELT AND HEAD AIRBAG	New	1,800.00	0.00
3	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOOR.TO CUT OUT AND WELD LHS SILL PANEL AND LHS B-PILLAR.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,500.00	1,500.00
4	TO RESPRAY LHS FRONT DOOR AND LHS REAR DOOR, HINGES, LHS SILL PANEL. LHS B-PILLAR, DOOR ENTRANCES, DOOR HANDLES AND LHS REAR FENDER	New	3,775.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		9,827.00	4,452.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >