

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010886/KPA3Q2

Date: 10/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100378000

Claimant
Vehicle No : SJA189R **Insured Vehicle No :** SKP8868X

Date of Loss: 08/10/2020 Nature of Claim: TP Claim No: 7513559783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA189R	Engine No:	BWA145538
Make & Model:	AUDI TTC, 2.0 TFSI S-TRONIC (A)	Chassis No:	TRUZZZ8J871038195
Reg. Date:	29/10/2007 (Man. Year: 2007)	Odometer:	140295 km
Colour:	Metallic Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35ZR19	Rear Tyre Size:	245/35ZR19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,861.75	7,021.80	6,839.95	49.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	2,290.00	2,160.00	48.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,311.75	9,311.80	8,999.95	49.15
Approved Total (Overridden) (\$\$)		7,450.00		
(\$\$)	18,311.75	7,450.00	10,861.75	59.32
+ GST 7.00/7.00% (\$\$)	1,281.82	521.50	760.32	59.32
Nett Amount (\$\$)	19,593.57	7,971.50	11,622.07	59.32
+ Car Rental (9.0 x \$S150.00/day + 7.00% GST) (\$\$)		1,444.50		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		9,418.00		

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 12/10/2020 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-15, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR GLASS RH	Serviceable	360.00 FL	*- FL
2	1		*DOOR GLASS MOULDING RH	Serviceable	80.00 FL	*- FL
3	1		*DOOR RH	Bent	2,700.00 FL	*2,450.00 FL
4	1		*DOOR SEAL RH	Serviceable	300.00 FL	*- FL
5	1		*DOOR RH HINGE UPPER	Repair	70.00 FL	*- FL
6	1		*DOOR RH HINGE LOWER	Repair	200.00 FL	*- FL
7	1		*REAR FENDER RH	Bent	760.00 FL	*760.00 FL
8	1		*REAR FENDER INNER SHIELD RH	Serviceable	160.00 FL	*- FL
9	10		*REAR FENDER INNER SHIELD CLIP	Not Necessary	80.00 FL	*- FL
10	1		*SIDE PANEL RH	Repair	2,000.00 FL	*- FL
11	1		*ROCKER PANEL GARNISH RH	Warped	600.00 FL	*600.00 FL
12	1		*REAR RH TIE ROD	Serviceable	200.00 FL	*- FL
13	1		*REAR KNUCKLE ARM RH	Bent	850.00 FL	*495.00 FL
14	1		*REAR KNUCKLE ARM BEARING RH	Necessary	300.00 FL	*300.00 FL
15	1		*REAR RH CONNECTING LINK	Serviceable	100.00 FL	*- FL
16	1		*STABILIZER LINK RH	Serviceable	250.00 FL	*- FL
17	1		*REAR RH SHOCK ABSORBER	Serviceable	300.00 FL	*- FL
18	1		*REAR BUMPER	Cracked	1,500.00 FL	*1,500.00 FL
19	1		*REAR BUMPER RETAINER RH	Distorted	75.00 FL	*75.00 FL
20	1		*REAR BUMPER SPONGE	Serviceable	100.00 FL	*- FL
21	4		*REAR BUMPER SENSOR	Serviceable	1,000.00 FL	*- FL
22	10		*REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
23	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*BODY SEALANT	Necessary	50.00 FS	*30.00 FS
25	1		*TYRE SPORT RIM	Dented	1,800.00 FS	*1,004.80 FS
26	1		*CONTINENTAL SPORT CONTACT 6 TYRE (RH REAR)	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,465.00	7,334.80
- List Item Discount on L Items 5.00/5.00% (\$\$)	603.25	313.00
Total Parts (\$\$)	13,861.75	7,021.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,600.00	900.00
2	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	100.00
3	TO REMOVE & REPLACE RH DOOR GLASS	New	100.00	60.00
4	TO REMOVE,RENEW & REFIT REAR RH TYRE	New	150.00	20.00
5	TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS	New	50.00	50.00
6	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	150.00	30.00
7	TO REMOVE & REFIT ALL SENSOR	New	100.00	50.00
8	TO RESET ENGINE WARNING LIGHT (SBS SRS ECU MEMORY & ETC)	New	200.00	0.00
9	TO REMOVE & REFIT REAR RH UNDERCARRIAGE	New	150.00	60.00
10	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	120.00	60.00
11	TO APPLY ANTI RUST COATING	New	80.00	60.00
12	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,600.00	900.00
Gross Labour Cost (\$\$)			4,450.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >