

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010887/ASD3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00114582001

**Claimant
Vehicle No :** SLM4363R

**Insured
Vehicle No :** SLH1772P

Date of Loss: 07/10/2020

Nature of
Claim: TP

Claim
No: SNM20D203761/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4363R**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD
5DR (A)

Engine No: HRA2330634A

Reg. Date: 30/03/2017 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1763950

Colour: White

Odometer: 169812 km

Engine Capacity: 1197 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17

Rear Tyre Size: 215/60R17

Front Left Side: Habilead 6 mm

Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,028.85	2,349.33	679.52	22.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,230.00	830.00	40.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	5,088.85	3,579.33	1,509.52	29.66
Approved Total (Overridden) (\$)		2,850.00		
(\$)	5,088.85	2,850.00	2,238.85	44.00
+ GST 7.00/7.00% (\$)	356.22	199.50	156.72	44.00
Nett Amount (\$)	5,445.07	3,049.50	2,395.57	44.00

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 12/10/2020 Inspected At:

2 KAKI BUKIT AVE 2

#01-17 AUTOHUB

Repairer: N-51 Automotive Pte Ltd

(kaki Bukit Autohub) (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM4363R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	755.40 FL	*755.40 FL
2	2		*REAR BUMPER REFLECTOR L/R	Cracked	110.00 FL	*110.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	619.20 FL	*619.20 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	71.80 FL	*71.80 FL
5	1		*REAR BUMPER SPONGE	Cracked	126.40 FL	*126.40 FL
6	1		*REAR BUMPER TOW HOOK COVER	Cut	16.80 FL	*16.80 FL
7	1		*REAR END PANEL	Dented	482.60 FL	*482.60 FL
8	1		*REAR END PANEL ANTENNA SENSOR	Cracked	285.10 FL	*98.00 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	63.50 FL	*63.50 FL
10	1		*REAR TAILGATE QASHQAI EMBLEM	Not Necessary	87.00 FL	*- FL
11	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	158.70 FL	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
13	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	450.00 FS	*200.00 FS
14	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,306.50	2,583.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	277.65	234.37
Total Parts (\$\$)	3,028.85	2,349.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR	New	60.00	30.00
2	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	50.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	500.00
4	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	600.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	50.00
Gross Labour Cost (\$\$)			2,060.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >