

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010888/ACD3E2

Date: 27/01/2021

REFERENCE

Insured/Claimant:	NG YI CHONG	Policy No:	2100503127		
Date of Loss:	07/10/2020	Nature of Claim:	OD	Claim No:	3027229377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1845U		
Make & Model:	OPEL INSIGNIA, 1.6 Turbo (A)	Engine No:	B1150435GKUX0098
Reg. Date:	30/03/2016 (Man. Year: 2015)	Chassis No:	W0LGS5E53F1035109
Colour:	Brown	Odometer:	95299 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,751.50	15,032.50	10,719.00	41.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,500.00	4,550.00	5,950.00	56.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,251.50	19,582.50	16,669.00	45.98
Approved Total (Overridden) (S\$)		10,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	35,751.50	10,000.00	25,751.50	72.03
+ GST 7.00/7.00% (S\$)	2,502.61	700.00	1,802.61	72.03
Nett Amount (S\$)	38,254.11	10,700.00	27,554.11	72.03

INSPECTION

Date of Assignment:	09/10/2020		
Date Inspected:	09/10/2020	Inspected At:	First Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 South Wing Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Repair	2,866.00 FL	*- FL
2	10		*FRT BONNET INSULATOR CLIP	Not Necessary	65.00 FL	*- FL
3	1		*FRT BONNET LOCK	Not Necessary	220.00 FL	*- FL
4	1		*FRT BONNET LOCK CABLE	Not Necessary	126.00 FL	*- FL
5	1		*FRT BONNET HINGE LH	Not Necessary	216.00 FL	*- FL
6	1		*FRT BONNET HINGE RH	Not Necessary	216.00 FL	*- FL
7	1		*FRT FENDER RH	Repair	902.00 FL	*- FL
8	1		*FRT FENDER INNERSHIELD RH	Torn	154.00 FL	*154.00 FL
9	10		*FRT FENDER INNERSHIELD CLIP	Necessary	65.00 FL	*65.00 FL
10	1		*FRT FENDER LH	Repair	902.00 FL	*- FL
11	1		*FRT FENDER INNERSHIELD LH	Not Necessary	154.00 FL	*- FL
12	1		*FRT BUMPER	Distorted	2,364.00 FL	*2,364.00 FL
13	1		*FRT BUMPER TOW COVER	Missing	156.00 FL	*156.00 FL
14	1		*FRT BUMPER LOWER CENTRE GRILLE	Deformed	194.00 FL	*194.00 FL
15	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*65.00 FL
16	1		*FRT BUMPER TOP CENTRE RETAINER	Cracked	172.00 FL	*172.00 FL
17	1		*FRT BUMPER SIDE RETAINER LH, SUPPORT	Damaged	134.00 FL	*134.00 FL
18	1		*FRT BUMPER SIDE RETAINER RH, SUPPORT	Damaged	134.00 FL	*134.00 FL
19	1		*FRT BUMPER BRACKET, LH, GUIDE	Damaged	120.00 FL	*120.00 FL
20	1		*FRT BUMPER BRACKET RH, GUIDE	Damaged	120.00 FL	*120.00 FL
21	1		*FRT BUMPER SPONGE UPP	Cracked	282.00 FL	*282.00 FL
22	1		*FRT BUMPER REINFORCEMENT, IMPACT BAR UPP	Bent	646.00 FL	*646.00 FL
23	1		*FRT BUMPER LOW LIP, RH	Not Necessary	246.00 FL	*- FL
24	1		*FRT BUMPER LOW LIP, LH	Not Necessary	246.00 FL	*- FL
25	1		*FRT BUMPER FOG LAMP COVER RH	Cut	380.00 FL	*380.00 FL
26	1		*FRT BUMPER FOG LAMP RH	Cracked	366.00 FL	*366.00 FL
27	1		*FRT BUMPER FOG LAMP COVER LH	Not Necessary	380.00 FL	*- FL
28	1		*FRT BUMPER FOG LAMP LH	Not Necessary	366.00 FL	*- FL
29	1		*FRT BUMPER PARKING SENSOR (2PCS)	Damaged (1Pc Only)	492.00 FL	*246.00 FL
30	2		*FRT BUMPER PARKING SENSOR SEAL	Necessary	13.00 FL	*13.00 FL
31	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Cracked	256.00 FL	*256.00 FL
32	1		*FRT GRILLE ASSY	Cracked	1,141.00 FL	*1,141.00 FL
33	1		*RH HEADLAMP	Cut	1,528.00 FL	*1,528.00 FL
34	1		*LH HEADLAMP	Cracked	1,528.00 FL	*1,528.00 FL
35	1		*FRT SUPORT PANEL TOP CENTRE	Repair	646.00 FL	*- FL
36	1		*A/C CONDENSER	Dented	1,498.00 FL	*1,498.00 FL
37	1		*A/C CONDENSER TOP AIR GUIDE	Not Necessary	130.00 FL	*- FL
38	1		*A/C CONDENSER AIR GUIDE RH	Not Necessary	102.00 FL	*- FL
39	1		*A/C CONDENSER AIR GUIDE LH	Not Necessary	154.00 FL	*- FL
40	1		*A/C PIPE (CONDENSER TO COMPRESSOR)	Not Necessary	675.00 FL	*- FL
41	1		*A/C PIPE (COOLING COIL TO CONDENSOR)	Not Necessary	504.00 FL	*- FL
42	1		*TURBO INTAKECOOLER	Dented	1,047.00 FL	*1,047.00 FL
43	1		*AIR HOSE (INTAKECOOLER TO THROTTLE BODY)	Not Necessary	669.00 FL	*- FL
44	1		*AIR HOSE (TURBO TO INTAKECOOLER)	Cut	555.00 FL	*555.00 FL
45	1		*FRT INTAKE AIR DUCT (TO RESONATOR BOX)	Cracked	415.00 FL	*415.00 FL
46	1		*FRT INTAKE RESONATOR BOX	Not Necessary	373.00 FL	*- FL
47	1		*RADIATOR	Cracked	1,495.00 FL	*1,495.00 FL
48	1		*RADIATOR TOP MOUNTING, INSULATOR	Not Necessary	16.00 FL	*- FL
49	1		*RADIATOR TOP BRACKET	Not Necessary	10.00 FL	*- FL
50	1		*RADIATOR LOW BRACKET	Damaged	34.00 FL	*34.00 FL
51	1		*RADIATOR TOP HOSE, INLET	Not Necessary	214.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR LOW HOSE, OUTLET	Not Necessary	254.00 FL	*- FL
53	1		*RADIATOR FAN ASSY	Not Necessary	912.00 FL	*- FL
54	1		*RADIATOR FAN COWLING	Cracked	835.00 FL	*835.00 FL
55	1		*FRT NUMBER PLATE	Deformed	65.00 FS	*35.00 FS
56	1		*RADIATOR COOLANT	Necessary	80.00 FS	*80.00 FS
57	1		*A.T.F	Not Necessary	60.00 FS	*- FS
58	1		*FRT BUMPER REINFORCEMENT LOW	Bent	384.00 FL	*384.00 FL
59	1		*ENGINE UNDER COVER RH	Torn	116.00 FL	*116.00 FL
60	1		*FRT BUMPER REINFORCEMENT LOW BRACKET RH	Damaged	132.00 FL	*132.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,590.00	16,690.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,838.50	1,657.50
Total Parts (\$\$)	25,751.50	15,032.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,900.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT FENDER RH, FRT FENDER LH, FRT SUPPORT PANEL, FRT DOOR RH, FRT DOOR LH	New	3,850.00	2,200.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	280.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	200.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	220.00	80.00
6	TO CONDUCT CHASIS ALIGNMENT OF VEHICLE	New	1,300.00	0.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	0.00
Gross Labour Cost (S\$)			10,500.00	4,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >