



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 7561X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,455.60	-
1	FUEL LIP	TO REPAIR SEE LABOUR	168.50	-
1	SLIDING DOOR N/S	TO REPAIR SEE LABOUR	1,655.10	-
	LESS 25% DISCOUNT		-	-
			3,279.20	-
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR N/S,FUEL LIP AND SLIDING DOOR N/S.		600.00	300.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	600.00
			1,860.00	900.00
	<b>GRAND TOTAL</b>		<b>5,139.20</b>	<b>900.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>900.00</b>
------------------------------------	--	--	---------------

Report Ref No. CS/SMO20010894/Utd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.