



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 6038C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,232.82	-
1	REAR BUMPER RETAINER RH	SERVICEABLE	50.75	-
1	REAR BUMPER CHROME RH	NECESSARY	188.65	145.00
1	REAR SPORT RIM RH	TO REPAIR SEE LABOUR	2,291.55	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	805.98	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,744.61	-
1	REAR WINDSCREEN GLASS WITH MOULDING	SERVICEABLE	998.21	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,871.65	-
1	REAR DOOR CHROME MOULDING RH	NECESSARY	288.63	230.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,882.74	-
1	FRONT DOOR CHROME MOULDING RH	NECESSARY	288.63	230.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	771.40	-
1	WING MIRROR ASSY RH	BROKEN	1,018.56	850.00
	LESS 10% DISCOUNT		-1,543.42	-145.50
			13,890.76	1,309.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	65.00	-
1	SET FRONT DOOR BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET REAR DOOR BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	REAR TYRE RH (SN)	SERVICEABLE	580.00	-
			835.00	-
<b><u>LABOUR</u></b>				
	REPAIR & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR SPORT RIM RH,REAR FENDER RH,REAR DOOR RH,FRONT DOOR RH AND FRONT FENDER RH.		1,200.00	400.00

Report Ref No. CS1/LPM20010896/Qvf3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT AFFECTED AREA.		1,500.00	1,000.00
	REMOVE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	260.00	-
	REMOVE & REFIX REAR TRIM BOARD & GARNISH.	NOT NECESSARY	120.00	-
	REMOVE & REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	REMOVE & REFIX BOTH DOOR MECHANISM.	NOT NECESSARY	300.00	-
	CHECK WHEEL ALIGNMENT (BEFORE & AFTER REPAIR).		240.00	60.00
			3,800.00	1,460.00
	<b>GRAND TOTAL</b>		<b>18,525.76</b>	<b>2,769.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>

Report Ref No. CS1/LPM20010896/Qvf3s2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.