

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Lee Ming Jie Blk 205 Petir Road #12-605 Singapore 670205	Date : 03/09/2018 Reference No : CAS/18-09/003
<u>General Information</u>	
Registration No. : SLK 6038C Accident Date : 24/08/2018	
<u>Particulars of Damaged Vehicle</u>	
Colour : Blue Engine Capacity : 1798 cc Mileage (KM) : 87802 Chassis No. : WVWZZZ3CZBE711536 Registration Date : 10/11/2010	Make & Model : Volkswagen Passat CC Pre-Accident Condition : Good Engine No. : CDA139770 Steering : In Order Brake : In Order
<u>Tyre Condition</u>	
R/H Front Tyre : 235/45R17 L/H Front Tyre : 235/45R17 R/H Rear Tyre : 235/45R17 L/H Rear Tyre : 235/45R17	Make : BRIDGESTONE Balance : 90% 90% 80% 80%
<u>Inspection</u>	
Repairer : Glockewerke 21 Kaki Bukit Road 4, #01-02, Singapore 417810	
<u>Adjustment And Recommendation Cost Of Repair</u>	
Repairer's Estimate : \$18,525.77 Revised Amount : \$14,000.00 Less Excess : - Nett Total : \$14,000.00	
<u>Remarks</u>	
(A) Survey was done on 25/08/2018 (B) Re-survey after repair was done on 29/08/2018 (C) The survey was conducted entirely on WITHOUT PREJUDICE basis. (D) We have NOT given any instruction to authorize the repair of the vehicle.	

2018 08 24
2010 11 10

7 9 14

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SLK 6038C

Our ref : CAS/18-09/003

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Rear bumper X R	Grazed/Torn	2,232.82	2,232.82 X
2	1pc	Rear bumper retainer RH X SVC	Serviceable	50.75	-
3	1pc	Rear bumper chrome RH / NEC	Grazed	188.65	188.65 145
4	1pc	Rear sport rim RH X R	Grazed/Cut	2,291.55	2,291.55 X
5	1pc	Rear shock absorber RH X SVC	Serviceable	805.98	-
6	1pc	Rear fender RH X R	Dented/Warped	2,744.61	2,744.61 X
7	1pc	Rear windscreen glass with moulding X SVC	Necessary	998.21	998.21 X
8	1pc	Rear door RH X R	Dented/Warped	1,871.65	1,871.65 X
9	1pc	Rear door chrome moulding RH / NEC	Grazed	288.63	288.63 230
10	1pc	Rear door RH X R	Dented/Warped	1,882.74	1,882.74 X
11	1pc	Front door chrome moulding RH / NEC	Grazed	288.63	288.63 230
12	1pc	Front fender RH X R	Repair	771.40	-
13	1pc	Wing mirror assy RH / BR	Broken	1,018.56	1,018.56 850
				15,434.18	13,806.05 1,455
Less 10%				(1,543.41)	(1,380.60) -10%
Sub total				13,890.77	12,425.45 1,309.50
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Rear windscreen glass sealant	Necessary	100.00	80.00 X
2	1set	Rear bumper clip	Necessary	65.00	65.00 X
3	1set	Front door board clip	Necessary	45.00	45.00 X
4	1set	Rear door board clip	Necessary	45.00	45.00 X
5	1pc	Rear tyre RH	Serviceable	580.00	-
Sub total				14,725.77	12,660.45
<u>LABOUR & MISC. CHARGES</u>					
1		Repair & replace damaged parts		1,200.00	1,000.00 400
2		Spray paint affected area		1,500.00	1,200.00 1,000
3		Remove & refix rear undercarriage	Not Necessary	260.00	-
4		Remove & refix rear trim board & garnish		120.00	80.00 X
5		Remove & refix rear windscreen glass		180.00	150.00 X
6		Remove & refix both door mechanism		300.00	240.00 X

Constant Appraiser Services

Vehicle No : SLK 6038C

Our ref : CAS/18-09/003

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
7		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
		Check wheel alignment (before & after repair)		240.00	200.00
			Grand total	18,525.77	15,530.45
Recommended cost of lump sum repair (To its pre-accident condition)					14,000.00

60
1460

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$14,000.00 on a contractual basis. Under normal circumstances, the repair period would be about 5 (Five) working days.

Repair day 3 days

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

P = 1,309.50
L = 1,460

2,769.50
- 20%

2,215.60

L/S
\$ 2,200
3 days