



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance and vehicle information for KCV14451/TAN JACK WEI.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX00008, Credit, 09/10/2020/ 12:07, QUD, 247 / DonBong, 58323

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REMOVE AND TRANSFER REAR TAILGATE AND OTHERS, etc.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**MITSUBISHI MOTORS**

CYCLE & CARRIAGE

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV14451/TAN JACK WEI (CHEN YIWEI)
	Reg No/Reg Date	SLB6106L / 15/04/201
	Date In/Mileage	/ 0
	Chassis No	JMFXTGA2WFZC10585
	Engine No	4B11QY7722
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	PO2 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	09/10/2020/ 12:07	QUD	247 / DonBong	58323

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
RENEW REAR EXHASUT SYSTEM				20 50.00
M SUNDRY				
SUNDRIES				
M W/STRIP, TAILGATE OPENING				del 149.38 ✓
M PANEL ASSY, TAILGATE				bt 870.10 ✓
M DAM, TAILGATE, LWR				net 20.79 ✓
M LATCH, TAILGATE				bt 294.91 ✓
M STRIKER, TAILGATE LATCH				nn 14.63 ✓
M HINGE, TAILGATE				Ry 43.12 ✓
M MARK, THREE-DIA				net 53.13 ✓
M MARK, ASX				net 43.12 ✓
M PANEL, RR END				bt 199.43 ✓
M PANEL, RR END, INR RH				bt 21.56 ✓
M PANEL, RR END, INR LH				nn 21.56 ✓
M TRIM, RR END				del 94.71 ✓
M REINFORCEMENT, RR BUMPER - photo				bt 179.41 ✓
M BRACKET, RR BUMPER				R 24.64 ✓
M GROMMET, SPLASH SHIELD				nn 3.08 ✓
M BRKT, R/BMPR FACE SUPT, LH				R 20.79 ✓
M FACE, RR BUMPER				del 681.45 ✓
M COVER, RR FOG LAMP				del 33.88 ✓
M MOULDING, RR WHEEL ARCH, LH				del 101.64 ✓
M MOULDING, RR WHEEL ARCH, RH				nn 101.64 ✓
M PROT, UNDER RR FLOOR HEAT				net 71.61 ✓
M MUFFLER, EXHAUST MAIN				bt 662.97 ✓
M PIPE, EXHAUST, CTR				bt 1592.36 ✓
M SILENCER, FLOOR				? 21.56 ✓
				bt 10.78 ✓
				(14.00) 23.00

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signatures  
 Date  
**Estimate**

SURVEYOR NAME: Taufik 97495719  
 SURVEYOR SIGNATURE: [Signature]  
 DATE: 9/10/20 @ 5pm  
 REMARKS: Not Authorise, Present

Confirm & accepted by	REMARKS:	Nett	12,161.47
<u>Taufik @ 11:20 am</u>	<u>Ex: to be advise, Resurvey before paint</u>	7% GST on	851.30
	<u>9 days</u>	<b>Total Payable</b>	<b>13,012.77</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.