

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010907/KPA3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800134009

Claimant
Vehicle No : SMU6499R **Insured Vehicle No :** GBE3962D

Date of Loss: 07/10/2020 Nature of Claim: TP Claim No: 5749238982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU6499R		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	1ZRX233535
Reg. Date:	26/11/2012 (Man. Year: 2012)	Chassis No:	MR053REE104151775
Colour:	Metallic Green	Odometer:	169718 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,545.96	5,966.44	579.52	8.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,870.00	930.00	33.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,345.96	7,836.44	1,509.52	16.15
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	9,345.96	5,900.00	3,445.96	36.87
+ GST 7.00/7.00% (S\$)	654.22	413.00	241.22	36.87
Nett Amount (S\$)	10,000.18	6,313.00	3,687.18	36.87
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,680.45		

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 09/10/2020 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Bent	881.90 FL	*881.90 FL
2	2		*FRONT DOOR HINGE	Repair	156.40 FL	*- FL
3	1		*FRONT DOOR CHECKER	Serviceable	138.20 FL	*- FL
4	1		*FRONT FENDER ,RH	Bent	602.40 FL	*602.40 FL
5	1		*FENDER COWLING	Distorted	236.70 FL	*236.70 FL
6	1		*COWLING CLIP	Necessary	38.00 FL	*38.00 FL
7	1		*FENDER TRIANGLE GARNISH	Missing	76.20 FL	*76.20 FL
8	1		*SIDE MIRROR ,RH	Cracked	980.00 FL	*980.00 FL
9	1		*MIRROR COVER	Dented	83.20 FL	*83.20 FL
10	1		*BONNET	Bent	978.20 FL	*862.90 FL
11	1		*FRONT BUMPER	Buckled	459.75 FL	*459.75 FL
12	1		*BUMPER RETAINER ,RH	Distorted	54.50 FL	*54.50 FL
13	1		*BUMPER CLIP	Necessary	42.00 FL	*42.00 FL
14	1		*HEADLAMP ,RH	Cracked	525.30 FL	*525.30 FL
15	1		*FRONT RH ABSORBER	Bent	356.90 FL	*356.90 FL
16	1		*KNUCKLE ARM ,RH	Bent	441.40 FL	*441.40 FL
17	1		*DRIVE SHAFT ,RH	Bent	1,633.40 FL	*1,410.60 FL
18	1		*WHEEL HUB	Bent	197.80 FL	*197.80 FL
19	1		*BEARING	Necessary	119.40 FL	*119.40 FL
20	1		*LOWER ARM RH	Distorted	326.30 FL	*326.30 FL
21	1		*RH TYRE	Serviceable	140.00 FL	*- FL
22	1		*RIM RH	Dented	260.00 FL	*260.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,727.95	7,955.25
- List Item Discount on L Items 25.00/25.00% (S\$)	2,181.99	1,988.81
Total Parts (S\$)	6,545.96	5,966.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/TRANSFER DOOR GLASS ,DOORBOARD ,POWER MECHANISM TO NEW DOOR	New	120.00	60.00
2	TO REMOVE DAMAGED PARTS AND ATTACHMENTS STRAIGHTEN CHASSIS WHERE NECESSARY REPAIR/RESHAPE ALL DAMAGED PANEL /AREAS RELACE /ALIGN ALL PARTS INTO POSITION	New	1,000.00	700.00
3	TO REPAIR /REPLACE UNDERCARRIAGE PARTS	New	400.00	200.00
4	COMPUTER ALIGNMENT	New	80.00	60.00
5	TO SPRAY PAINT	New	1,200.00	850.00
Gross Labour Cost (\$\$)			2,800.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >