



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102380

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/04/2021
Reference CC6/CTI20010913/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SBA 5995S
Insured Veh. GBE 4809H
Claim No. SNM20D203814/C02
Policy No. DMCVSNW000009862000
Accident Date 08/10/2020
Inspection Date 09/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20010913/Upa3q2	
			Date: 09/04/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 4809H	Veh. Inspected	SBA 5995S	
Policy No.	DMCVSNW000009862000	Coverage (\$)	0.00	
Claim No.	SNM20D203814/C02	Excess (\$)	0.00	
Assign From		Assign Date	09/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE (A)	c.c	3456	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GGH300005617	Colour	WHITE	
Odometer	121358 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R20	CONTINENTAL	7 mm	
L/H Front Tyre	255/40 R20	CONTINENTAL	7 mm	
R/H Rear Tyre	255/40 R20	CONTINENTAL	7 mm	
L/H Rear Tyre	255/40 R20	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/10/2020	Inspection Date	09/10/2020	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBA 5995S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	297.45	188.45
1	REAR TAILGATE	BADLY DENTED	1,997.42	1,997.42
2	REAR TAILGATE HINGE RH/LH @\$78.20	NOT NECESSARY	156.40	-
2	REAR TAILGATE ABSORBER RH/LH @\$299.60	NOT NECESSARY	599.20	-
1	REAR TAILGATE RUBBER LH (POWER GATE CONTROL SENSOR)	NOT NECESSARY	405.22	-
1	REAR TAILGATE WEATHERSTRIP	TWISTED	399.45	399.45
1	REAR TAILGATE LOCK	DENTED / SHORTED	509.43	509.43
1	REAR TAILGATE LOK CATCH	NOT NECESSARY	43.10	-
1	REAR TAILGATE KEYLESS SMART	CRACKED	243.50	243.50
1	REAR TAILGATE KEYLESS BUZZLE	CRACKED	220.35	220.35
1	REAR TAILGATE INNER TRIM	DEFORMED / TWISTED	718.13	718.13
1	REAR TAILGATE POWER GATE CONTROL SWITCH	SHORTED / CRACKED	309.14	309.14
1	REAR TAILGATE EMBLEM "VELLFIRE"	NECESSARY	96.80	96.80
1	REAR TAILGATE EMBLEM "V6"	NECESSARY	95.10	95.10
1	REAR TAILGATE REFLECTOR LH	NOT NECESSARY	499.36	-
1	REAR TAILLAMP LH	SCRATCHED / CRACKED	695.43	695.43
1	REAR TAILLAMP LOWER APRON GARNISH LH	DEFORMED	266.80	266.80
1	REAR TAILLAMP LOWER APRON GARNISH RETAINER LH	BENT	131.60	131.60
1	REAR BUMPER	DEFORMED	1,918.43	1,755.10
1	REAR BUMPER TOW COVER LH	DEFORMED	69.10	69.10
1	REAR BUMPER BRACKET LH	SERVICEABLE	145.20	-
2	REAR BUMPER PDC SENSOR @\$399.45	SHORTED	798.90	798.90
2	REAR BUMPER SIDE RETAINER RH/LH @\$145.23	N/S BENT	290.46	145.23
1	REAR END PANEL	BADLY DENTED	755.23	755.23
1	REAR END PANEL GARNISH	TWISTED	395.45	395.45
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	798.50	-
1	REAR SPARE TYRE PANEL TRIM	SERVICEABLE	509.40	-

Report Ref No. CC6/CTI20010913/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL CARDBOARD-CENTRE	WARPED	335.20	335.20
2	REAR SPARE TYRE PANEL CARDBOARD RH/LH @ \$394.45	N/S WARPED	788.90	394.45
1	REAR FENDER INNER TRIM LH	DEFORMED / TORN	899.45	899.45
	LESS 25% DISCOUNT		-3,847.03	-2,854.93
			11,541.07	8,564.78
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
			135.00	95.00
	LABOUR			
	TO KNOCK OUT DENT,CUT/WELD REAR PANEL,REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS.		1,200.00	800.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,200.00	900.00
	TO CHECK WIRING.		30.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.00
	TO REMOVE AND REFIX CUSHION AND INNER TRIM.		120.00	80.00
	TO REFIX REVERSE CAMERA,REAR CAMERA AND REPLACE REVERSE SENSOR.		150.00	50.00
	TO REMOVE,REFIX REAR EXHAUST BOX.	NOT NECESSARY	120.00	-
	TO REMOVE,REFIX FUEL TANK.	NOT NECESSARY	120.00	-
	TO TUFF-KOTE.		90.00	60.00
			3,250.00	2,100.00
GRAND TOTAL			14,926.07	10,759.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CC6/CTI20010913/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBA 5995S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBA 5995S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBA 5995S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBA 5995S

RE-INSPECTION

