



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20010915/Aqf3q2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 09-11-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | SJT 5473K | Veh. Inspected | GBK 6386R |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | C10007557/KY | Excess (\$) | 0.00 |
| Assign From | IVY RATILLA | Assign Date | 09/10/2020 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | NISSAN CABSTAR | c.c | 1998 |
| Engine No. | HIDDEN | Year of Reg. | 2020 |
| Chassis No. | JN1SA2F24Z0000150 | Colour | SILVER |
| Odometer | 521 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 175/80 R15 | YOKOHAMA | 6 mm |
| L/H Front Tyre | 175/80 R15 | YOKOHAMA | 6 mm |
| R/H Rear Tyre | 155 R13 | YOKOHAMA | 6 mm |
| L/H Rear Tyre | 155 R13 | YOKOHAMA | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 08/10/2020 | Inspection Date | 12/10/2020 |
| Survey held at | CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|