

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010917/ESD3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900091718

Claimant
Vehicle No : SJN8545A **Insured Vehicle No :** SML5983M

Date of Loss: 07/10/2020 Nature of Claim: TP Claim No: 1646538102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN8545A	Engine No:	3ZZ4792164
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106116977
Reg. Date:	02/03/2009 (Man. Year: 2008)	Odometer:	106789 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65R15	Rear Tyre Size:	175/65R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,502.87	1,975.78	5,527.09	73.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,992.00	1,620.00	1,372.00	45.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,494.87	3,595.78	6,899.09	65.74
Approved Total (Overridden) (\$\$)		2,900.00		
Nett Amount (\$\$)	10,494.87	2,900.00	7,594.87	72.37

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 09/10/2020 Inspected At: Yi Heng Motor Workshop (HQ)
Blk 1 Kaki Bt Ave 6 #02-19
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	544.21 FL	*- FL
2	10		*FRONT BUMPER CLIPS	Not Necessary	89.00 FL	*- FL
3	1		*FRONT BUMPER SIDE ATTACHMENT (RH)	Not Necessary	48.65 FL	*- FL
4	1		*FRONT FENDER (RH)	Dented	484.00 FL	*484.00 FL
5	1		*FRONT FENDER EMBLEM (RH)-VVT-I	Necessary	67.75 FL	*67.75 FL
6	1		*FRONT FENDER INNER SHIELD (RH)	Not Necessary	231.00 FL	*- FL
7	10		*FRONT FENDER INNER SHIELD CLIPS (RH)	Not Necessary	89.00 FL	*- FL
8	1		*FRONT SPORT RIM (RH)	Cut	478.00 FL	*350.00 FL
9	1		*FRONT SHOCK ABSORBER (RH)	Not Necessary	453.20 FL	*- FL
10	1		*FRONT KNUCKLE ARM (RH)	Not Necessary	438.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM BEARING (RH)	Not Necessary	231.00 FL	*- FL
12	1		*FRONT LOWER ARM (RH)	Not Necessary	328.00 FL	*- FL
13	1		*FRONT LOWER ARM BALL JOINT (RH)	Not Necessary	128.19 FL	*- FL
14	1		*FRONT WHEEL BEARING HUB (RH)	Not Necessary	283.00 FL	*- FL
15	1		*WING MIRROR (RH)	Repair	538.00 FL	*- FL
16	1		*WING MIRROR COVER (RH)	Not Necessary	138.90 FL	*- FL
17	1		*FRONT DOOR (RH)	Dented	863.00 FL	*863.00 FL
18	1		*FRONT DOOR STICKER (RH)	Necessary	93.70 FL	*93.70 FL
19	1		*FRONT DOOR PROTECTOR (RH)	Cut	183.00 FL	*183.00 FL
20	1		*FRONT DOOR GLASS OUTER CHROME MOULDING (RH)	Not Necessary	163.00 FL	*- FL
21	2		*FRONT DOOR HINGE (RH)	Bent	162.52 FL	*162.52 FL
22	1		*FRONT DOOR CHECKER (RH)	Not Necessary	187.40 FL	*- FL
23	1		*FRONT DOOR WEATHERSTRIPE (RH)	Not Necessary	144.20 FL	*- FL
24	1		*FRONT DOOR INNER TRIM BOARD (RH)	Not Necessary	780.10 FL	*- FL
25	1		*FRONT DOOR GLASS CHANNEL (RH)	Not Necessary	84.70 FL	*- FL
26	1		*FRONT DOOR GLASS REGULATOR (RH)	Bent	171.20 FL	*171.20 FL
27	1		*FRONT DOOR GLASS REGULATOR MOTOR (RH)	Not Necessary	236.20 FL	*- FL
28	1		*FRONT DOOR LOCK (RH)	Jammed	259.20 FL	*259.20 FL
29	1		*FRONT DOOR STRIKER (RH)	Not Necessary	48.40 FL	*- FL
30	1		*REAR DOOR (RH)	Repair	793.37 FL	*- FL
31	1		*REAR DOOR PROTECTOR (RH)	Not Necessary	144.80 FL	*- FL
32	1		*REAR DOOR STICKER (RH)	Not Necessary	141.60 FL	*- FL
33	1		*ROCKER GARNISH (RH)	Repair	573.00 FL	*- FL
34	8		*ROCKER GARNISH CLIPS (RH)	Not Necessary	71.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*FRONT TYRE (RH)	Not Necessary	250.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					9,920.49	2,634.37
- List Item Discount on L Items 25.00/25.00% (\$)					2,417.62	658.59
Total Parts (\$)					7,502.87	1,975.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	30.00
3	TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY (RH)	New	32.00	0.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	60.00
5	TO REMOVE AND REFIX FRONT & REAR DOOR (RH) FIXING AND REALIGNMENT	New	440.00	0.00
6	TO REPLACE NEW PARTS,CUT,WELD,KNOCK ETC	New	1,100.00	500.00
7	TO RESPRAY ON AFFECTED AREAS	New	1,100.00	1,000.00
Gross Labour Cost (\$\$)			2,992.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >