

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 15 Oct 2020

Preliminary Advice

Vehicle No	: SMU2922L	Accident Date	: 24/09/2020
Make	: ASTON MARTIN DBS	Policy No.	: DMPCSNW00102512000
Assignment Date	: 09/10/2020	Excess	: S\$18,000.00
Date of Inspection	: 12/10/2020	Est. Duration of Repair	: 60
Inspection At	: BRITISH MOTOR SERVICES (HQ) 56 LOYANG WAY #02-10 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	220,634.00
Revised Amount	:S\$	192,155.60
Check Items (Estimated)	:S\$	5,569.30
Total	:S\$	197,724.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	300,000.00
COE / PARF Rebate	:S\$	202,205.00
Salvage Value	:S\$	
Margin for Repair	:S\$	97,795.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.