

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010922/EBA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800008738
Claimant Vehicle No :	SHD4761U	Insured Vehicle No :	SLW1033K
Date of Loss:	09/10/2020	Nature of Claim:	TP
		Claim No:	3778008126SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4761U		
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 (A)	Engine No:	G4LEKU210993
Reg. Date:	14/05/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU146228
Colour:	Blue	Odometer:	99248 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,740.40	5,527.20	1,213.20	18.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,900.00	260.00	12.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,900.40	7,427.20	1,473.20	16.55
+ GST 7.00/7.00% (\$\$)	623.03	519.90	103.13	16.55
Nett Amount (\$\$)	9,523.43	7,947.10	1,576.33	16.55
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Car Rental (5.0 x S\$128.40/day) (\$\$)		642.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		8,841.10		

INSPECTION

Date of Assignment:	09/10/2020	
Date Inspected:	09/10/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

2/16/2021

Adjuster Report

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER BRACKET TOP LH	Not Necessary	35.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET LH	Broken	28.00 FL	*28.00 FL
4	1		*FRONT BUMPER CENTRE MOULDING	Cut	188.00 FL	*188.00 FL
5	1		*FRONT BUMPER GRILLE LH	Cut	186.90 FL	*186.90 FL
6	1		*DAY LIGHT LH	Cut	642.50 FL	*642.50 FL
7	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*HEADLAMP LH	Cut	1,993.65 FL	*1,993.65 FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	949.30 FL	*- FL
10	1		*FRONT FENDER LH	Dented	490.70 FL	*490.70 FL
11	1		*FRONT WHEEL HUB CAP LH	Cut	346.40 FL	*346.40 FL
12	1		*FRONT FENDER SHIELD LH	Not Necessary	114.70 FL	*- FL
13	1		*EMBLEM BLUE-DRIVE LH	Necessary	26.60 FL	*26.60 FL
14	1		*FRONT DOOR LH	Dented	1,797.20 FL	*1,797.20 FL
15	1		*FRONT DOOR HINGE UPPER LH	Not Necessary	65.76 FL	*- FL
16	1		*FRONT DOOR HINGE LOWER LH	Not Necessary	65.76 FL	*- FL
17	1		*FRONT DOOR CHECK LH	Not Necessary	72.98 FL	*- FL
18	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	78.00 FL	*- FL
19	1		*ROCKER PANEL GARNISH GARNISH LH	Broken	290.00 FL	*290.00 FL
20	1		*FRONT TYRE LH (80%)	Torn	216.00 FS	*108.00 FS
21	1		*FRONT FENDER ADVERTISEMENT LH	Necessary	100.00 FS	*100.00 FS
22	1		*FRONT DOOR COMFORT LOGO LH	Necessary	75.00 FS	*75.00 FS
23	1		*FRONT DOOR ADVERTISEMENT LH	Necessary	100.00 FS	*100.00 FS
					Sub Total (S\$)	8,302.75
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,562.35
					Total Parts (S\$)	6,740.40
						5,527.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	960.00
2	SPRAY PAINTING	New	900.00	800.00
3	REMOVE/REFIX DOOR ASSY	New	120.00	50.00
4	WHEEL ALIGNMENT	New	90.00	60.00
5	CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			2,160.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >