

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2007760

INV Date 18/11/2020

Reference CC4/FCI20010925/Epa3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 9735T

Insured Veh. SH 8896L

Claim No. D20004091MFSH

Policy No. D-20094922MFSH

Accident Date 07/10/2020

Inspection Date 09/10/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

MS FIRST CAPITAL INSURANCE LTD Ref : CC4/FCI200	10925/Epa3q2		
	' '		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 Date: 18-11-2020 Code: FCI2			
1. Policy Particulars :- THIRD PARTY CL	.AIM		
Insured Veh. SH 8896L Veh. Inspected GBG 9735T			
Policy No. D-20094922MFSH Coverage (\$)	0.00		
Claim No. D20004091MFSH Excess (\$)	0.00		
Assign From CHRIS LIM Assign Date	09/10/2020		
2. Vehicle Particulars & Condition			
Make & Model NISSAN NV350 c.c	2488		
Engine No. HIDDEN Year of Reg.	2017		
Chassis No. JN1MC2E26Z0009805 Colour	WHITE		
Odometer 105719 Steering	IN ORDER		
Brakes IN ORDER Modification	STANDARD ALLOY RIM		
General FAIR			
3. Conditions of Tyres			
Size Make	Balance		
R/H Front Tyre 185 R15C GOODYEAR	5 mm		
L/H Front Tyre 185 R15C GOODYEAR	5 mm		
R/H Rear Tyre 185 R15C GOODYEAR	5 mm		
L/H Rear Tyre 185 R15C GOODYEAR	5 mm		
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date 07/10/2020 Inspection Date	09/10/2020		
Survey held at EFFICIENT MOTOR & ENGINEERING WORKS PTE L	_TD		
56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUI	LDING SINGAPORE 508775		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" B B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHOR	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS		
5b. Estimate Days of Repair	* *		
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 9735T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	667.20	667.20
2	REAR BUMPER ABSORBER LH/RH @\$132.00	NOT NECESSARY	264.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	228.30	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	324.00	-
1	TAILGATE	DENTED	2,160.00	2,160.00
1	TAILGATE LOCK LOWER	NOT NECESSARY	384.00	-
1	TAILGATE LOCK UPPER	BENT	178.80	178.80
1	TAILGATE LOCK COVER	NOT NECESSARY	84.00	-
1	TAILGATE LOCK ACTUATOR	NOT NECESSARY	408.40	-
1	TAILGATE STRIKER	NOT NECESSARY	51.50	-
1	TAILGATE WEATHERSTRIP	TORN	228.00	137.50
1	TAILGATE CHROME GARNISH	NOT NECESSARY	535.70	-
2	TAILGATE STAY @\$215.90	NOT NECESSARY	431.80	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	220.00	-
1	TAILGATE LOGO	NECESSARY	115.20	60.00
1	TAILGATE EMBLEM 'NV350 URBAN'	NECESSARY	156.00	89.00
1	TAILGATE INNER CENTER METAL COVER	NOT NECESSARY	108.00	-
2	TAIL LAMP LH/RH @\$264.80	O/S BROKEN	529.60	264.80
1	EXHAUST SILENCER	NOT NECESSARY	1,320.00	-
	LESS 10% DISCOUNT		-839.45	-355.73
			7,555.05	3,201.57
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	70KM/H STICKER (SN)	NECESSARY	20.00	20.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR NO PLATE (SN)	NOT NECESSARY	45.00	-
1	PAN PACIFIC METAL PLATE (SN)	NECESSARY	80.00	50.00
1	BACK DOOR GLASS SEALANT (SN)	NECESSARY	80.00	40.00
			475.00	340.00

Report Ref No. CC4/FCI20010925/Epa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO PANEL BEAT & ALIGN REAR PANEL,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	600.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.		100.00	30.00
	TO CHECK AND RECTIFY LIGHTING & WIRING .		50.00	30.00
	TO REMOVE & REPLACE REVERSE SENSOR .		100.00	30.00
	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS.		1,000.00	800.00
	TO REMOVE & TRANSFER TAILGATE COMPONENTS.		150.00	50.00
	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS .		150.00	120.00
	TO REMOVE AND REFIT AND ALIGN EXHAUST SILENCER .	NOT NECESSARY	100.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		50.00	30.00
			2,700.00	1,690.00
	GRAND TOTAL		10,730.05	5,231.57

ſ	RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
	(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/FCI20010925/Epa3q2



CHEN TSUE YEE

Automotive Assessor



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 9735T

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

