3/12/23, 8:54 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010926/KPA3Q2

12/03/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800015044 **Claimant Vehicle** GZ1097U Insured Vehicle No: SLW4028G

No:

Date of Loss: 07/10/2020 Nature of Claim: TP Claim No: 4903301771SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GZ1097U

Make & Model: NISSAN URVAN 5DR(D), 3.0 (A) ZD30018670K Engine No:

Reg. Date: 09/12/2005 (Man. Year: 2005) Chassis No: JN1MG4E25Z0713853

Colour: White Odometer: 906537 km

Engine Capacity: 2953 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 195 R15X8 Rear Tyre Size: Front Left Side: Michelin 7 mm Rear Left Side: Bridgestone 5 mm Front Right Side: Michelin 7 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,476.20	1,891.80	1,584.40	45.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	2,270.00	1,030.00	31.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,776.20	4,161.80	2,614.40	38.58
Approved Total (Overridden) (S\$)		700.00		
Nett Amount (S\$)	6,776.20	700.00	6,076.20	89.67
+ Loss of Use (2.0 x S\$	100.00/day) (S\$)	200.00		
+ Doc/s	Search Fee (S\$)	2.00		
N	ett Liability (S\$)	902.00		
Global Sum	Settlement (S\$)	900.00		

INSPECTION

Date of Assignment: 09/10/2020

Goldbell Engineering Pte Ltd (Ang Mo Kio) Date Inspected: 15/10/2020 Inspected At:

Blk 5035 Ang Mo Kio Industrial Park 2,, #01-367

Singapore 569538

Estimated Period of Repair: 0.0 days

CHEW HSIAO TONG Adjuster: KENNETH KONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/12/23, 8:54 PM Adjuster Report

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$1,500.00

LTA REIMBURSEMENT VALUE (RV) : \$747.00

NETT VALUE : \$753.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	565.00 FL	*565.00 FL
2	1		*FRONT BUMPER	Torn	862.00 FL	*862.00 FL
3	1		*FRONT BUMPER BRACKET LH	* Check	50.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET LH	* Check	50.00 FL	*- FL
5	1		*FOG LAMP LH	Serviceable	485.00 FL	*- FL
6	1		*FOG LAMP COVER LH	Dented	152.00 FL	*152.00 FL
7	1		*CORNER PANEL LH	Bent	698.00 FL	*698.00 FL
8	1		*FRONT DOOR LH	Repair	1,467.00 FL	*- FL
9	1		*FRONT DOOR HINGE UPPER	Repair	95.00 FL	*- FL
10	1		*FRONT DOOR HINGE LOWER	Repair	95.00 FL	*- FL
11	1		*SIDE STEP LH	Dented	397.00 FL	*397.00 FL
12	1		*ROC STICKER	Necessary	35.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	4,951.00	2,694.00
			- List Item Discount on I	_ Items 30.00/30.00% (S\$)	1,474.80	802.20
				Total Parts (S\$)	3,476.20	1,891.80
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
<u>Lab</u>	our Items					
1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	1,800.00	1,200.00		
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	20.00		
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	1,400.00	1,050.00		
	Gross Labour Cost (S\$)		3,300.00	2,270.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >