

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20010933/GES3Q2
Date: 27/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLK7534E	Insured Vehicle No :	SHC8113U
Date of Loss:	07/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7534E		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB741677
Reg. Date:	25/01/2017 (Man. Year: 2015)	Chassis No:	ZSU600073819
Colour:	White	Odometer:	53257 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,516.40	1,703.07	813.33	32.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	740.00	1,390.00	65.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,646.40	2,443.07	2,203.33	47.42
	+ Loss of Use (3.0 x S\$80.00/day) (S\$)	240.00		
	+ Doc/Search Fee (S\$)	7.49		

Nett Liability (S\$)	2,690.56
-----------------------------	-----------------

INSPECTION

Date of Assignment: 09/10/2020

Date Inspected: 07/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Tropical Success Auto Care (HQ)
BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2
Singapore 569535

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK7534E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,469.00 FL	*1,302.80 FL
2	1		*REAR BUMPER PARKTRONIC SENSOR KIT	Damaged	360.00 FS	*200.00 FS
3	1		*REAR BUMPER LOWER LIP	Cracked	465.00 FL	*465.00 FL
4	2		*REAR BUMPR REFLECTOR	Not Necessary	132.00 FL	*- FL
5	2		*REAR BUMPER SIDE BRACKET (LONG)	Deformed	180.00 FL	*130.00 FL
6	1		*REAR BUMPER SPONGE	Cracked	150.00 FL	*106.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,756.00	2,204.10
- List Item Discount on L Items 10.00/25.00% (S\$)	239.60	501.03
Total Parts (S\$)	2,516.40	1,703.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS }	New	600.00	200.00
2	REMOVE AND REFIT REAR BUMPER ,REAR BUMPER PARKTRONIC SENSOR KIT ,REAR BUMPER LOWER LIP ,REAR BUMPER REFLECTOR ,REAR BUMPER SIDE BRACKET (LONG) REAR BUMPER SPONGE }	New	0.00	0.00
3	HEAT /WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	0.00	0.00
4	TUFF KOTE REAR DAMAGED PORTION	New	150.00	0.00
5	DIAGNOSTIC REAR PARKTRONIC SENSOR FAULT ERROR BY HHT	New	180.00	40.00
6	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR END PANEL,REAR BUMPER	New	1,200.00	500.00
Gross Labour Cost (S\$)			2,130.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >