

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010961/ATD3E2

Date: 06/05/2021

REFERENCE

Insured/Claimant:	ANG KIM CHOO	Policy No:	1800108959	
Date of Loss:	03/10/2020	Nature of Claim:	OD	Claim No: 6978573758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3551R		
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Engine No:	CZE671923
Reg. Date:	11/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA9JA089964
Colour:	Grey	Odometer:	26374 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,555.00	2,360.80	9,194.20	79.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,972.00	1,522.00	1,450.00	48.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,527.00	3,882.80	10,644.20	73.27
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	13,727.00	3,082.80	10,644.20	77.54
+ GST 7.00/7.00% (S\$)	960.89	215.80	745.09	77.54
Nett Amount (S\$)	14,687.89	3,298.60	11,389.29	77.54

INSPECTION

Date of Assignment:	12/10/2020		
Date Inspected:	09/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	195.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	167.00 FS	*133.60 FS
5	1		*FRONT BUMPER END CAP - LH	Not Necessary	34.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	296.00 FS	*236.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	154.00 FS	*- FS
8	1		*WHEEL SPOILER - LH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	35.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,395.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	123.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	679.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	77.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	99.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	35.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
17	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
18	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Not Necessary	4,859.00 FS	*- FS
20	1		*LIFT CYLINDER - LH	Not Necessary	141.00 FS	*- FS
21	2		*FRONT WHEEL COVER - LH / RH	Not Necessary	636.00 FS	*508.80 FS
22	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,555.00 2,360.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,000.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,100.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,972.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >