

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010966/EGS3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800134987

Claimant
Vehicle No : SHD3314J **Insured Vehicle No :** SMF6504M

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 4637045130SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3314J		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU111710
Reg. Date:	24/10/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU114995
Colour:	Blue	Odometer:	198094 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,268.12	4,705.32	562.80	10.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,270.00	280.00	18.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,818.12	5,975.32	842.80	12.36
+ GST 7.00/7.00% (\$\$)	477.27	418.27	59.00	12.36
Nett Amount (\$\$)	7,295.39	6,393.59	901.80	12.36
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Car Rental (4.5 x S\$128.40/day) (\$\$)		577.80		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,173.39		
Global Sum Settlement (\$\$)		7,150.00		

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 12/10/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Broken	430.90 FL	*430.90 FL
2	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*BRACKET -FR BUMPER	Broken	28.00 FL	*28.00 FL
4	1		*BRACKET -FR BUMPER	Broken	35.00 FL	*35.00 FL
5	1		*MOULDING -FRONT	Cut	188.00 FL	*188.00 FL
6	1		*MOULDING -FRT BUMP	Broken	85.10 FL	*85.10 FL
7	1		*LAMP ASSY -HEAD	Cut	1,993.65 FL	*1,993.65 FL
8	1		*LAMP ASSY -DAY R	Cut	642.50 FL	*642.50 FL
9	1		*MOULDING -FRONT	Cut	93.60 FL	*93.60 FL
10	1		*PANEL -FENDER RH	Repair	588.80 FL	*- FL
11	1		*EMBLEM -BLUE DRIVE	Necessary	26.60 FL	*26.60 FL
12	1		*GUARD ASSY -FRONT	Not Necessary	114.70 FL	*- FL
13	1		*FRT FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
14	1		*FRT BUMPER REINFORCEMENT	Bent	1,075.10 FL	*1,075.10 FL
15	1		*FRT SUPPORT PANEL	Broken	949.30 FL	*949.30 FL
16	1		*FRT BUMPER GRILLE LOWER	Broken	186.90 FL	*186.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,560.15	5,856.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,292.03	1,151.33
Total Parts (\$\$)	5,268.12	4,705.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING (REPAIR BONNET)	New	800.00	640.00
2	SPRAYPAINT ON AFFECTED AREA	New	650.00	600.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	0.00
Gross Labour Cost (\$\$)			1,550.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >