

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20010971/R1VD3Q2

**Date:** 04/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNA00002042004	
Claimant Vehicle No : SCJ1928D	Insured Vehicle No : SKZ2324K	
Date of Loss: 08/10/2020	Nature of Claim: TP	Claim No: SNM20D203783/C02/TKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SCJ1928D</b>	Engine No: L15Z11414235
Make & Model: HONDA CITY, 1.5 (A)	Chassis No: MRHGM6660EP000125
Reg. Date: 18/11/2014 (Man. Year: 2014)	Odometer: 78574 km
Colour: Maroon	
Engine Capacity: 1497 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size: 185/55 R16	Rear Tyre Size: 185/55 R16
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,777.00	526.54	2,250.46	81.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,890.00	3,420.00	2,470.00	41.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,667.00</b>	<b>3,946.54</b>	<b>4,720.46</b>	<b>54.46</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	606.69	276.26	330.43	54.46
<b>Nett Amount (\$\$)</b>	<b>9,273.69</b>	<b>4,222.80</b>	<b>5,050.89</b>	<b>54.46</b>

### INSPECTION

Date of Assignment:	12/10/2020	
Date Inspected:	19/10/2020 Inspected At:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
<b>Parts:</b>	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCJ1928D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACERR.BUMPER	Deformed	440.51 FS	*440.51 FS
2	1		*REFLECTOR ASSYR.RR	Serviceable	15.77 FS	*- FS
3	1		*REFLECTOR ASSYL.RR	Serviceable	15.77 FS	*- FS
4	1		*SPACER R.RR.BUMPER SIDE	Necessary	10.92 FS	*10.92 FS
5	1		*SPACER L.RR.BUMPER SIDE	Serviceable	10.92 FS	*- FS
6	1		*CLIP,BUMPER (4 PCS)	Necessary	8.74 FS	*8.74 FS
7	1		*PANEL COMPRR	Serviceable	346.27 FS	*- FS
8	1		*LINING ASSYRR PANEL	Serviceable	63.27 FS	*- FS
9	1		*TAILLIGHT ASSY R	Serviceable	195.41 FS	*- FS
10	1		*PANEL SETR.RR.OUTSIDE	Repair	1,213.05 FS	*- FS
11	4		*ACT RR SENSOR	Serviceable	320.00 FS	*- FS
12	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
13	1		*EMBLEM H	Necessary	11.68 FS	*11.68 FS
14	1		*EMBLEMRR.CITY	Necessary	12.06 FS	*12.06 FS
15	1		*EMBLEMRR.I-VTEC	Necessary	12.63 FS	*12.63 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>2,777.00</b>
						<b>526.54</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE & RENEW REVERSE SENSORS	New	280.00	280.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	280.00	280.00
3	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	New	3,250.00	1,300.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,080.00	1,560.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,890.00</b>	<b>3,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >