



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV08661/Mr Tan Su Wai
	Reg No/Reg Date	SMA7829X / 20/06/201
	Date In/Mileage	/ 74387
	Chassis No	GF7W0401722
	Engine No	4J11YC2390
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER. RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR								2250.00
E PNT88000	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK								100.00
A 55900099	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								80.00
E PNT98000	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, LH FRONT DOOR, RH FRONT DOOR AND AFFECTED PORTION								2800.00
M SUNDRY	APPLY BODY SEALANT								120.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY	SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY	PERFORM RUST PREVENTION								80.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY	RE-APPLY ZERTONA PAINT PROTECTION								480.00
M SUNDRY	SUNDRIES								50.00
M PNL,HEADLAMP SUPT,UPR RH					1.00	58.00	23.00	44.66	
M PANEL,HEADLAMP SUPPORT,UPR					1.00	182.00	23.00	140.14	
M PNL,HEADLAMP SUPT,UPR LH					1.00	58.00	23.00	44.66	
M PNL,HEADLAMP SUPT,UPR LH					1.00	58.00	23.00	44.66	
M PANEL,HEADLAMP SUPPORT,LWR					1.00	146.00	23.00	112.42	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV08661/Mr Tan Su Wai
	Reg No/Reg Date	SMA7829X / 20/06/201
	Date In/Mileage	/ 74387
	Chassis No	GF7W0401722
	Engine No	4J11YC2390
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL,HEADLAMP SUPPORT,LWR	1.00	155.00	23.00	119.35			
M	CONDENSER ASSY,A/C REFRIGE	1.00	857.00	23.00	659.89			
M	RADIATOR ASSY	1.00	1091.00	23.00	840.07			
M	TANK ASSY,RADIATOR COND	1.00	103.00	23.00	79.31			
M	FAN,COOLING,LH	1.00	78.00	23.00	60.06			
M	FAN,COOLING,LH	1.00	78.00	23.00	60.06			
M	SHROUD,COOLING FAN	1.00	258.00	23.00	198.66			
M	MOTOR,COOLING FAN,LH(120W)	1.00	479.00	23.00	368.83			
M	MOTOR,COOLING FAN,LH(120W)	1.00	479.00	23.00	368.83			
M	LLC 4L	1.00	26.00	23.00	20.02			
M	BRACKET,RADIATOR GRILLE,RH	1.00	17.00	23.00	13.09			
M	BRACKET,RADIATOR GRILLE,LH	1.00	13.00	23.00	10.01			
M	HOOD	1.00	975.00	23.00	750.75			
M	HINGE,HOOD,LH	1.00	68.00	23.00	52.36			
M	HINGE,HOOD,RH	1.00	68.00	23.00	52.36			
M	INSULATOR,HOOD	1.00	133.00	23.00	102.41			
M	WEATHERSTRIP,HOOD	1.00	40.00	23.00	30.80			
M	LATCH,HOOD	1.00	76.00	23.00	58.52			
M	FENDER,FR LH	1.00	688.00	23.00	529.76			
M	FENDER,FR RH	1.00	688.00	23.00	529.76			
M	MOULDING,FR BUMPER,LH	1.00	116.00	23.00	89.32			
M	MOULDING,FR BUMPER,RH	1.00	116.00	23.00	89.32			
M	MOULDING,FR WHEEL ARCH,LH	1.00	199.00	23.00	153.23			
M	MOULDING,FR WHEEL ARCH,RH	1.00	199.00	23.00	153.23			
M	HEADLAMP ASSY,LH	1.00	2125.00	23.00	1636.25			
M	HEADLAMP ASSY,RH	1.00	2125.00	23.00	1636.25			
M	LAMP ASSY,FOG,FR LH	1.00	348.00	23.00	267.96			
M	LAMP ASSY,FOG,FR RH	1.00	348.00	23.00	267.96			
M	BRACKET,FR BUMPER SIDE,LH	1.00	18.00	23.00	13.86			
M	BRACKET,FR BUMPER SIDE,RH	1.00	18.00	23.00	13.86			
M	FACE,FR BUMPER	1.00	859.00	23.00	661.43			
M	EXTENSION,FR BUMPER	1.00	426.00	23.00	328.02			
M	GARNISH,FR BUMPER,LH	1.00	75.00	23.00	57.75			

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV08661/Mr Tan Su Wai
	Reg No/Reg Date	SMA7829X / 20/06/201
	Date In/Mileage	/ 74387
	Chassis No	GF7W0401722
	Engine No	4J11YC2390
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH,FR BUMPER,RH	1.00	75.00	23.00	57.75
M COVER,FR BUMPER	1.00	294.00	23.00	226.38
M GARNISH,FR BUMPER SIDE	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE	1.00	69.00	23.00	53.13
M REINF,FR BUMPER SIDE,RH	2.00	22.00	23.00	33.88
M REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20
M REINFORCEMENT,FR BUMPER	1.00	134.00	23.00	103.18
M BAR,FR BUMPER GUARD	1.00	130.00	23.00	100.10
M BAR,FR BUMPER GUARD	1.00	130.00	23.00	100.10
M REINFORCEMENT,FR BUMPER	1.00	503.00	23.00	387.31

Estimate

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

7% GST on	18,513.11	1,295.92
Total Payable	19,809.03	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

