Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010976/UYD3Q2

Date: 10/11/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNA00001962000

Claimant Vehicle No:

SMD1307J

Insured Vehicle No:

Claim:

SMH1191D

Date of Loss:

08/10/2020

Nature of TP

Claim SNM20D203778/C02/TKL No:

L15Z16201870

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMD1307J Reg No:

Make & Model: HONDA CITY, 1.5 (A)

Reg. Date: 02/08/2018 (Man. Year: 2018)

> Odometer: 40345 km

Engine No:

Chassis No:

MRHGM6660KT000247

Colour: Blue 1497 cc

Engine Capacity: Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 185/55R16 185/55R16 Rear Tyre Size: Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,749.03	39.66	2,709.37	98.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,460.00	3,500.00	4,960.00	58.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,209.03	3,539.66	7,669.37	68.42
+ GST 7.00/7.00% (S\$)	784.63	247.78	536.85	68.42
Nett Amount (S\$)	11,993.66	3,787.44	8,206.22	68.42

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 19/10/2020 Inspected At: Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4 Singapore 408610

Estimated Period of Repair: 5.0 days

Manager: YVONNE WONG YIN CHENG Adjuster: MARCUS CHUA

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Nov 2020)

Parts: 143 HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD1307J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANELR SIDE SILL	Repair	1,116.06 FS	*-FS
2	1		*PANEL COMPR RR DOOR	Repair	676.87 FS	*-FS
3	1		*TAPER.RR DOOR SASH CENTER	Not Necessary	14.63 FS	*-FS
4	1		*DISK,ALUMINIUM WHEEL 16X6J	Serviceable	431.30 FS	*-FS
5	1		*FACE,RR BUMPER	Repair	440.51 FS	*-FS
6	1		*SPACER R RR BUMPER SIDE	Necessary	10.92 FS	*10.92 FS
7	1		*CLIP,BUMPER (4 Pcs)	Necessary	8.74 FS	*8.74 FS
8	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcN	lett.	_		
				Total Parts (S\$)	2,749.03	39.66
				_		

O-----

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	WHEEL ALIGNEMNTX4	New	180.00	0.00			
2	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	New	150.00	0.00			
3	REMOVE & INSTALL REVERSE SENSOR-4 PCS	New	180.00	130.00			
4	BODY JOINT SEALANT	New	100.00	0.00			
5	BODY UNDERSIDE COATING	New	100.00	0.00			
6	APPLY BODY UNDERSIDE COATING	New	250.00	0.00			
7	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	0.00			
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	250.00			
9	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADJUST	New	500.00	0.00			
10	CUT OFF & RENEW R SILL PANEL, STRAIGHTEN ALIGN	New	3,300.00	1,300.00			
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	2,800.00	1,820.00			
	Gross Labour Cost (S\$)		8,460.00	3,500.00			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >