

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010983/R1PS3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070114801

Claimant
Vehicle No : SDV50S **Insured Vehicle No :** SMU8190S

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 4864412207SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV50S		
Make & Model:	BMW 335I, 3.0 (A)	Engine No:	09028065N55B30A
Reg. Date:	21/08/2020 (Man. Year: 2020)	Chassis No:	WBA3A92000F095696
Colour:	Grey	Odometer:	85562 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,031.90	1,961.70	70.20	3.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,863.00	4,225.00	3,638.00	46.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,894.90	6,186.70	3,708.20	37.48
+ GST 7.00/7.00% (\$\$)	692.64	433.07	259.57	37.48
Nett Amount (\$\$)	10,587.54	6,619.77	3,967.77	37.48
+ Loss of Use (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,021.77		

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 11/01/2021 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT RH SIDE PANEL	Bent	706.15 FS	*706.15 FS
3	1		*FRT RH 2 SIDE PANEL BRACKET	Serviceable	35.10 FS	*- FS
4	1		*FRT RH 3 SIDE PANEL BRACKET	Serviceable	35.10 FS	*- FS
5	1		*INSCRIPTION SIDE (SPORT LINE)	Necessary	46.75 FS	*46.75 FS
6	1		*ALLOY RIM 8JX18 DOUBLE SPK STY 397	Scratched	1,127.30 FS	*1,127.30 FS
7	3		*RIVET	Necessary	1.50 FS	*1.50 FS
					Total Parts (S\$)	2,031.90 1,961.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE RIGHT FRONT WHEEL RIMS	New	94.00	94.00
2	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATION	New	451.00	451.00
3	TO REPLACE FRONT RIGHT SIDE PANEL TO REMOVE AND INSTALL BUMPER FRONT COVER AND ATTACHMENTS	New	5,100.00	1,700.00
4	TO SPRAY PAINT BUMPER FRONT COVER AND FRONT RIGHT SIDE PANEL	New	1,923.00	1,730.00
5	TO CARRY OUT BODY CAVITYPRESER VATION (PER PANEL)	New	118.00	100.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$)			7,863.00	4,225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >