

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010988/AGS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800089048

Claimant
Vehicle No : SMF9994L **Insured Vehicle No :** GBG3880X

Date of Loss: 11/10/2020 Nature of Claim: TP Claim No: 5804691824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9994L		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX030893
Reg. Date:	30/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF2J2125132
Colour:	Bronze	Odometer:	35633 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,120.00	7,394.64	26,725.36	78.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,672.00	2,622.00	3,050.00	53.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	39,792.00	10,016.64	29,775.36	74.83
+ GST 7.00/7.00% (\$\$)	2,785.44	701.16	2,084.28	74.83
Nett Amount (\$\$)	42,577.44	10,717.80	31,859.64	74.83
+ Car Rental (4.0 x S\$150.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		11,319.80		

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 13/10/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,595.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	267.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	222.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	142.00 FS	*- FS
5	1		*FRONT SPOILER	Not Necessary	754.00 FS	*- FS
6	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	474.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	3,490.00 FS	*2,792.00 FS
9	1		*QUATTRO INSCRIPTION	Necessary	95.00 FS	*75.36 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	241.00 FS	*192.80 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	Not Necessary	1,148.00 FS	*- FS
12	2		*FRONT BUMPER END CAP -LH /RH	Not Necessary	182.00 FS	*- FS
13	4		*LOCKING CLIP	Not Necessary	15.00 FS	*- FS
14	2		*FRONT PARKING AID SENSOR -INNER	Not Necessary	484.00 FS	*- FS
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	285.00 FS	*- FS
17	1		*FRONT BUMPER CARRIER	Not Necessary	911.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
19	1		*AIRCON STICKER	Not Necessary	20.00 FS	*- FS
20	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
21	1		*BONNET	Dented	4,012.00 FS	*3,209.60 FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTOR -LH	Necessary	28.00 FS	*21.84 FS
24	1		*BONNET IMPACT PROTECTOR -RH	Necessary	27.00 FS	*21.52 FS
25	1		*BONNET IMPACT PROTECTOR -CENTRE	Necessary	27.00 FS	*21.52 FS
26	2		*HEADLIGHT MOUNTING -LH/RH	Not Necessary	234.00 FS	*- FS
27	2		*LED HEADLIGHT -LH/RH	Not Necessary	15,862.00 FS	*- FS
28	2		*LIFT CYLINDER -LH /RH	Not Necessary	276.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE -LH/RH	Not Necessary	116.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE -UPPER	Not Necessary	48.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE -CENTRE	Not Necessary	42.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE -LOWER	Not Necessary	48.00 FS	*- FS
33	2		*FRONT WHEEL COVER -LH/RH	Necessary	1,250.00 FS	*1,000.00 FS
34	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **34,120.00** **7,394.64**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND HEADLIGHTS .RE-ORGANISE CRASH MANGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,500.00	1,000.00
4	TO RESPRAY FRONT BUMPER ,FRONT BUMPER LOWER SPOILER ,BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	2,700.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,672.00	2,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >